

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDX344J (Insd veh)	Model:	BMW X5 XL 3.0 (A)
	SMR2323G (TP veh)		
Date of Accident:	20/11/2020		

Global Sum Settlement	:	[ ] Yes	[ X ] No
Repair Estimate	:	\$	<b>3,148.64</b>
Final Repair Cost	:	\$	2,482.03
Loss of Use	:	\$	330.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,814.03
Is Third Party Workshop GIA Registered? [ X ] YES [ ] NO (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability _____ (%)	
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: <u>27</u>	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 2,814.03
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Apr  
2021

LKK Auto Consultants Pte Ltd

Date

**Please attach all the supporting documents to the form.**

**(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))**