

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 25 November

To : LKK

Attn : Bryan

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FW 9551A

Yamaha 125Z

ACCIDENT DATE: 11 November 2020

	Description	Qty	Quotation \$
	1 Handle Bar broken <i>distorted</i>	1	195.00 X ✓
	2 Brake Lever <i>cut o/s</i>	1	85.00 ✓
	3 Mirror <i>HI</i>	1 set	160.00 X
	4 Balancer <i>o/s cut</i>	1	150.00 ✓
	5 Brake Reservoir <i>HI</i>	1	195.00 X
	6 Front Fender <i>cut</i>	1	245.00 ✓
	7 Front Tube broken <i>distorted</i>	1 set	480.00 X ✓
	8 Front Rim <i>HI</i>	1	325.00 X
	9 Horn Cover <i>HI</i>	1	90.00 X
Front	10 Rear LH Side Panel <i>cut</i>	1	165.00 ✓
Front	11 Rear RH Side Panel <i>broken</i>	1	190.00 ✓
	12 Exhaust Guard broken <i>cut HI</i>	1	180.00 X <i>part X</i>
	13 Clutch Lever <i>HI</i>	1	95.00 X
	14 Footrest Rubber <i>HI</i>	1	68.00 X
	15 Throttle Cable broken <i>HI broken</i>	1	135.00 X ✓
	16 Front Visor <i>HI</i>	1	230.00 X
	17 Head Lamp Cover broken <i>cut</i>	1	250.00 X ✓
<i>Side Stand - 8 1/2</i>			Sub-Total 3,238.00
			Less 10% 323.80
<i>AT Pump Cover - 105-w</i>			Sub-Total 2,914.20
<i>broken</i>			

2085-w
1876.50

VEHICLE NO : FW 9551A

Yamaha 125Z

Nett Items

- 1 Rear box *SVL*
- 2 Towing fee *HH*
- 3 Remove & replace necessary parts,
align & etc
- 4 Remove & replace fork tube, top up
fork oil, replace fork rim
- 5 Putty & touch up paint work
- 6 ~~2~~ pcs front number plate *hec*
1

420.00 X

40.00 X

~~250.00~~ 120/-

295.00
~~150.00 HH~~ 80/-

~~220.00~~ 80/-

~~30.00~~ 15/-

Sub-Total

1,110.00

Nett Total

4,024.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

2171.50

4/S 1700/-

25/11/2020 @ 1730hrs

N/A Accident

2/Prm

1 year

3 days.

S9 MOTOR TRADING PTE LTD

:LG

LKK Auto

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: