

[illegible]

<u>Special nett item</u>					
5	1	rear windscreen sealant	✓	NEC	60.00 40 ✓
6	1	rear RH rim	✓	CUT	300.00 ✓
7	1	rear RH tyre	✗	NN	250.00 ✗
TOTAL					610.00
					340

To remove and replaced damaged parts including straightening and repositioning replacement parts.

Supply paint material and necessary items. To respray replaced and other affected panels.	600.00	400
to remove and reinstall bootlid components	80.00	×
To check wiring system for proper functions.	50.00	30
to remove and reinstall rear boot upholstery	100.00	× 50

To carry out anti rust treatment.	100.00	30
to remove and reinstall reversse sensor	80.00	30
to perform 4 wheel alignment	80.00	60
to remove and reinstall rear windscreen	120.00	✓

Total labour 1810.00 1200

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Steve (LKK)
Without Prejudice
26/11/20, 4.00 pm
6 repair days
L/S

Resurvey After Spray

P - 2019.60

N - 340

L - ~~1200~~ 1320

= ~~3559.60~~ 3679 60

L/S - ~~2847.68~~ 2943 60

= ~~2850~~ 2950