



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20011077/Qvd3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 02-12-2020



ATTN : LOH CHEE HENG

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 3987P	Veh. Inspected	SFR 787Y
Policy No.	1800023539	Coverage (\$)	0.00
Claim No.	3853250711SG	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	12/11/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 250CGI	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2120472A080323	Colour	SILVER
Odometer	137747	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R17	GOODYEAR	6 mm
L/H Front Tyre	245/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	245/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	245/45 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/10/2020	Inspection Date	13/10/2020
Survey held at	KEE YONG AUTOMOBILE SERVICE 160 SIN MING DRIVE, #03-09, SIN MING AUTOCITY, SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------