## Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)

Sent: Thursday, 3 December 2020 9:40 AM

To: 'tlauto'

Subject: RE: AIG-OD GBH 7542R DOA: 16/11/2020 -- Supplementary

**Attachments:** GBH7542R-Supplementary.pdf

Dear Candy,

Please proceed repair the supplementary of GBH 7542R and refer to the attached of our surveyor's marked supplementary list.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tlauto <tlauto@singnet.com.sg>
Sent: Tuesday, 1 December 2020 4:24 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: RE: AIG-OD GBH 7542R DOA: 16/11/2020 -- Supplementary

Dear Shiau Chan,

Please find attached Supplementary item pertaining to the above vehicle for your information

Kindly seek the approval from AIG and revert soonest

Best Regards, Candy Ong Tong Luck Auto Pte Ltd

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Tuesday, December 1, 2020 12:01 PM

To: <a href="mailto:tlauto@singnet.com.sg">tlauto@singnet.com.sg</a>
Cc: SUR <sur@lkkauto.com>

Subject: AIG-OD GBH 7542R DOA: 16/11/2020

Dear Candy,

As instructed by our client, please proceed to repair the insured vehicle GBH 7542R (Excess \$1,400/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Best Regards,

**Shiau Chan (Ms)** | Case Handler **LKK Auto Consultants Pte Ltd** 

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)