

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Dec 2020)
 Parts: N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/GBF9958Y/01/12/2020 15:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	Sen *280.00F
2	1		*1 PC FRT RH HEADLAMP	0.00	0.00	CM *210.00F
3	1		*1 PC FRT PANEL	0.00	0.00	Ry *480.00F
4	1		*1 PC FRT GRILLE	0.00	0.00	Red *310.00F
Total Parts (S\$)						1,280.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBF9958Y/01/12/2020 15:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC FRT WINDSCREEN SEALANT	40.00
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) TO REMOVE AND REFIX FRT WINDSCREEN GLASS	New	100.00
2	2) TO REMOVE AND REFIX DASH BOARD, METER ASSY TO FACILITATE ON REPAIRS	New	230.00
3	3) TO REMOVE AND REFIX AIRCON, CHECK AND VACUUM GAS	New	100.00
4	4) TO PANEL BEATING	New	550.00
5	5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT RH FENDER, FRT BUMPER	Repair	550.00
Gross Labour Cost (S\$)			1,530.00

Cheng Hoe Motor Pte Ltd/GBF9958Y/01/12/2020 15:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: