



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20013048/QKtf3n2 Date: 28/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 8549B	Veh. Inspected	SJL 6610T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003459/LOR	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/11/2020
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61143243	Colour	BLUE
Odometer	145750 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	FIRENZA	6 mm
L/H Front Tyre	185/60 R15	FIRENZA	6 mm
R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/11/2020	Inspection Date	26/11/2020
Survey held at	ELITE AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	