



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Ng Hai Kiat
	Reg No/Reg Date	SL25267K# / 08/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MJ5765707
	Engine No	G4FGJH695883
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	26/11/2020/ 16:01	QUD	247 / DonBong	23572		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR PANEL 480 RH REAR DOOR PANEL							800 1200.00
E PNT88000 REMOVE AND TRANSFER RH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL							120.00
E PNT98000 PAINT WORK SPRAY RH FRONT DOOR PANEL, RH REAR DOOR PANEL 350 AND AFFECTED PORTION * RH Side panel - cut							1050.00
M SUNDRY APPLY BODY SEALANT							80 120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							40 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 REMOVE AND TRANSFER RH REAR DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY SUNDRIES							20 50.00
M PANEL ASSY-FRONT DOOR, RH				1.00	1542.00	20.00	1233.60
M COVER-FR DR O/S HDL, DRIVER				1.00	22.00	20.00	17.60
M HANDLE ASSY-DOOR OUTSIDE				1.00	58.00	20.00	46.40
M BASE ASSY-FR DR O/S HANDLE RH				1.00	52.00	20.00	41.60
M LATCH ASSY-FRONT DOOR, RH				1.00	253.00	20.00	202.40
M CHECKER ASSY-FRONT DOOR, RH				1.00	32.00	20.00	25.60
M BLACK TAPE-FR DR FRAME UPR, RH				1.00	13.00	20.00	10.40
M BLACK TAPE-FR DR RR, RH				1.00	12.00	20.00	9.60

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	/Ng Hai Kiat
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SLZ5267K# / 08/05/201
78 SHENTON WAY #08-16	Date In/Mileage	/ 0
ATG BUILDING	Chassis No	KNAFX411MJ5765707
SINGAPORE 079120	Engine No	G4FGJH695883
Contact No 64191000	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	26/11/2020/ 16:01	QUD	247 / DonBong	23572			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-REAR DOOR,RH ✓				1.00	1361.00	20.00	1088.80
M	COVER-FR DR O/S HDL,PASSENGER X				1.00	22.00	20.00	17.60
M	HANDLE ASSY-DOOR OUTSIDE X				1.00	58.00	20.00	46.40
M	BASE ASSY-FR DR O/S HANDLE RH X				1.00	52.00	20.00	41.60
M	LATCH ASSY-REAR DOOR,RH X				1.00	309.00	20.00	247.20
M	BLACK TAPE-RR DR FRAME UPR,RH ✓				1.00	11.00	20.00	8.80
M	TAPE-RR DR FRAME BLACK RR,RH ✓				1.00	8.00	20.00	6.40

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Steve CLKK 26/11/20, 4.34pm

SURVEYOR SIGNATURE: DD- Not Auth

DATE: EXCIS - ?

REMARKS: 5 days

P/P

My Bel say

Confirm & accepted by

7% GST on	Nett	6,094.00
	6094.00	426.58
Total Payable		6,520.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.