LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Abu Kassim, Noor Mariesa Date: 30 Nov 2020

Preliminary Advice

Vehicle No : SMR1135P Accident Date : 23/11/2020 Make : AUDI Q5 SPORT Policy No. : 1900259405 Assignment Date : 27/11/2020 **Excess** : S\$500.00 Date of Inspection : 26/11/2020 Est. Duration of Repair : 10

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	70,399.00
Revised Amount	:S\$	31,065.00
Check Items (Estimated)	:S\$	4,650.00
Total	:S\$	35,715.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 185,000.00 COE / PARF Rebate 72,418.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 112,582.00

Remarks

()	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :