

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:48

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016300 Date : 19/05/2021 Order : SMR1135P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMR1135P (V 43282) Regn Date: 19/12/2019 Mileage: 13300 WIP No.: 58697

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZF7YK2123300 Engine: DAX 058077 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: RNP - TO SUPPLY VEHICLE NUMBER PLATE	60.00	1.00	60.00
S	BODYWORK	M: TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER WINDOW DEVICES.	500.00	1.00	500.00
S	BODYWORK	M: TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS.TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	560.00	1.00	560.00
S	BODYWORK	M: TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIRCOOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER AND BONNET.TO RENEW LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET,BOTH FRONT FENDER,BOTH FRONT WHEEL ARCH TRIMS,BOTH FRONT DOOR AND BOTH FRONT UPPER A PILLAR.	4800.00	1.00	4,800.00
S	BODYWORK	M: TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:48

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016300 Date : 19/05/2021 Order : SMR1135P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMR1135P (V 43282) Regn Date: 19/12/2019 Mileage: 13300 WIP No.: 58697

Model: Q5 SPORT 2.0 TFSI qu S Tronic Chassis: WAUZZZF7K2123300 Engine: DAX 058077 Dept: U

You have been assisted by :- UB-Lim Kee Siang (43)

		Details	Qty	Unit Price	Amount
X	A80A807107A GRU	008545/(V) (GER) COVER	Less 020%	1.00	1196.00
X	A80A807108A GRU	COVER (LAST)	Less 020%	1.00	1196.00
X	A80A807661 GRU	CONN PIECE (LAST)	Less 020%	1.00	202.50
X	A80A853651J RP5	(SK) GRILLE	Less 020%	1.00	3490.00
X	A80A853736 2ZZ	INSCRIPTION 'QUATTRO	Less 020%	1.00	94.20
X	A80A853692	PLATE (LAST)	Less 020%	1.00	241.00
X	A80A807679D RU6	(A) (SK) GRILL 3/12/20	Less 020%	1.00	573.50
X	A80A807550C	FOAM INSER (LAST) AP	Less 020%	1.00	285.00
X	A80A821106A STL	FENDER (LAST)	Less 020%	1.00	1411.00
X	A80A821132A STL	SUPPORT (LAST) AP	Less 020%	1.00	222.00
X	A80A823029 STL	HOOD (LAST)	Less 020%	1.00	4012.00
X	A80A823124	PROTECTION	Less 020%	1.00	26.90
X	A80A823125	PROTECTION	Less 020%	1.00	27.30
X	A80A823126	PROTECTION	Less 020%	1.00	26.90
X	A8N0853601A	INSCRIPTION "S-LINE"	Less 020%	2.00	122.00
X	A80A805607	(A) (SK) MOUNTING AP	Less 020%	1.00	117.00
X	A80A805608	MOUNTING (LAST) AP	Less 020%	1.00	117.00
X	A80A941773A	HEADLIGHT AP	Less 020%	1.00	7931.00
X	A80A941774A	HEADLIGHT	Less 020%	1.00	7931.00
X	A80A853717E GRU	COVER (LAST)	Less 020%	1.00	625.00
X	A80A853718E GRU	COVER (LAST)	Less 020%	1.00	625.00
X	A80A805594B	CARRIER (LAST) AP	Less 020%	1.00	1384.00
X	AG 12E040M2	COOLANT -25°C AP	Less 020%	4.00	44.20
X	A80A121673H	AIR DUCT AP	Less 020%	1.00	57.20
X	A80A121674H	AIR DUCT AP	Less 020%	1.00	57.20
X	A80A853283L 3Q7	008545/(V) (GER) WINDO	Less 020%	1.00	608.50
X	A80A853284L 3Q7	WINDOW SLO (LAST)	Less 020%	1.00	608.50
X	A80A821131A STL	SUPPORT AP	Less 020%	1.00	222.00
X	A80A820582C	COVER AP	Less 020%	1.00	30.50
X	A80A807284A	GUIDE AP	Less 020%	1.00	37.70
Sub-Total					37,513.36
7% GST					2,625.94
Grand Total					40,139.30

Parts 27,021.36
Labour 0.00
Sublet 10,992.00
Menus 0.00
Lubricant 0.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd