

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

320 UBI ROAD 3
Singapore 408649
Email: denisteo@cdge.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
FURUTANI YOSHIO

Singapore

Claimant Insurer: Liberty Insurance Pte Ltd

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/11/2020
Vehicle Reg. No.:	SLM4398R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	FURUTANI YOSHIO		
Make/Model:	OPEL ASTRA, 1.4 HB (A)	Vehicle Reg. Date:	30/03/2017
Vehicle Colour:	BLUE		
Engine No:	B1162637GSGX0344	Chassis No:	WOLBE6ECXHG023691
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (UBI)		

COST OF CLAIMS	Amount
Parts	6,270.80
Miscellaneous Items	11.00
Labour	2,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	8,861.80
+ GST 7.00% (\$)	620.33
Nett Amount (\$)	9,482.13

This claim is handled by: TINIE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2020)
Parts:	144	OPEL ASTRA 1.4 HB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SLM4398R/25/11/2020 12:39	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TAIL GATE	0.00	0.00	*1,560.00 F
2	1		*REAR TAIL GATE LOCK	0.00	0.00	*168.00 F
3	1		*ASTRA WORDING	0.00	0.00	*60.00 F
4	1		*TURBO WORDING	0.00	0.00	*60.00 F
5	1		*OPEL LOGO PLUS HANDLE	0.00	0.00	*132.00 F
6	1		*REAR BUMPER	0.00	0.00	*780.00 F
7	15		*REAR BUMPER CLIPS	0.00	0.00	*2,700.00 F
8	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*384.00 F
9	1		*REAR BUMPER SPONGE / BRACKET	0.00	0.00	*48.00 F
10	1		*REAR BUMPER LOWER GARNISH	0.00	0.00	*204.00 F
11	2		*REAR BUMPER REFLECTOR LAMP	0.00	0.00	*60.00 F
12	1		*REAR BUMPER TOW COVER	0.00	0.00	*54.00 F
13	1		*REAR END PANEL	0.00	0.00	*384.00 F
14	2		*REAR REVERSE SENSOR (ORIGINAL)	0.00	0.00	*168.00 F
15	1		*NUMBER PLATE	0	0.00	*45.00 FS
16	1		*SEALANT	0	0.00	*80.00 FS
17	1		*INNER SEAL	0	0.00	*60.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,947.00
- Add. Disc. on L,N Items 10.00% (\$\$)	676.20
Total Parts (\$\$)	6,270.80

ComfortDelGro Engineering Pte Ltd/SLM4398R/25/11/2020 12:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKET AND ETC	New	100.00
2	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	160.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	120.00
4	TO CUT & WELD REAR END PANEL , KNOCK AND REPAIR REAR SPARE TYRE PANEL AND AFFECTED AREA .	New	850.00
5	TO PUTTY & SPRAY PAINTING REAR TAIL GATE , REAR BUMPER , REAR END PANEL , REAR SPARE TYRE PANEL AND AFFECTED AREA	New	1,350.00
Gross Labour Cost (S\$)			2,580.00

ComfortDelGro Engineering Pte Ltd/SLM4398R/25/11/2020 12:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >