

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Nov 2020 14:53	Clm Veh Model Changed	(205158) KIA CERATO 1.6 (A).	[] Merimen Administrator
2	26 Nov 2020 14:53	Clm Created	Reg No: SMT7826D. Policy No: 2070106804. Acct Date: 2020/11/25. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MCC620105290	[I] Merimen Administrator
3	30 Nov 2020 10:05	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	30 Nov 2020 10:05	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	30 Nov 2020 10:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	30 Nov 2020 10:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/12/09	[A] LEE SU THING
7	30 Nov 2020 10:05	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	30 Nov 2020 10:05	Clm Registration Modified	Rep:1137->200074.	[A] LEE SU THING
9	30 Nov 2020 10:05	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
10	30 Nov 2020 13:09	Adj Rpt Initiated		[A] HUEY YON
11	30 Nov 2020 13:09	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
12	30 Nov 2020 13:09	Clm Dtl Modified	JPJ Reg. Date: -> 2020/07/17.	[A] HUEY YON
13	30 Nov 2020 13:09	Clm Details Notified		[A] HUEY YON
14	30 Nov 2020 14:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/12/09	[A] SHIAU CHAN
15	30 Nov 2020 14:18	Adj Mandate Request	Cur.Req:14162.80:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	30 Nov 2020 16:47	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Nadaraja, Deeban
17	30 Nov 2020 16:47	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	30 Nov 2020 18:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/12/09. Mandate Remarks: Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo require on (rocker panel, Rear fender) - after PUTTY FILLER	[I] Chang, Lois-KL
19	30 Nov 2020 18:15	Adj Mandate Set	Approved:12654.00:Re-inspection require on hidden part, check item, supplementary part with clear photo. Note: Before painting photo require on (rocker panel, Rear fender) - after PUTTY FILLERReinsp:Yes.	[I] Chang, Lois-KL

Date From    Date To    Audit Type None  Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2649671	30 Nov 2020 13:09:38	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMT7826D		11.00

2650624	01 Dec 2020 09:42:51	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SMT7826D	SHIAU CHAN	xx.xx
---------	-------------------------	--------------	-------	---	--	----------	------------	-------