

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Soh

Date: 26 Jan 2021

## **Preliminary Advice**

Insured Vehicle No : GBB8988M

TP Vehicle No : SMD4645M

Make : HONDA ACCORD

Date of Inspection : 30/11/2020

Inspection At : Ryder Auto Pte Ltd

Accident Date : 27/11/2020

Assignment Date : 30/11/2020

Est. Duration of Repair : 6

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,231.44
Revised Amount	:S\$	5,100.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,100.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a "Without Prejudice" basis.