



CYCLE & CARRIAGE

AG - OD CLAIM
SURVEY: 30/11/20
LHK - STEVE

VEHICLE NO : SMQ 2932D

MODEL : KIA/CERATO 1.6 A GT LINE

WIP : 25072

Material	:	\$	<u>10,681.60</u>
Labour	:	\$	<u>7,210.00</u>
Sub-Total	:	\$	<u>17,891.60</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>17,291.60</u>
GST 7%	:	\$	<u>1,210.41</u>
Grand Total	:	\$	<u>18,502.01</u>

Re-Finalise By/Date : LARRY ON 02/02/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 17 WORKING DAYS + 6 days (3 weekends)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/12/2020	Cust No/Name	LCV11454/LAI ZHEN NAN (LI ZHENNAN)
	Reg No/Reg Date	SMQ2932D*ECB1/ 07/11/2019
	Date In/Mileage	30/11/2020/ 21108
	Chassis/Package	KNAF5416MK5052954 /KC17
	Engine No	G4FGKH749533
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	02/02/2021/ 09:36	BLK	884 / Lauro Songcuan	25072

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, BONNET, BOTH FRONT FENDER & AFFECTED AREAS				1600.00 ✓
E PNT98000 SPRAY PAINT ON FRONT BUMPER, BONNET, BOTH FRONT FENDER & FRONT LH DOOR				2400.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A 15900099 REMOVE & INSTALL ENGINE ASSY				400.00 ✗
E PNT88000 REPAIR BOTH FRONT CHASSIS, BOTH WHEEL HOUSING & REPLACE SUPPORT PANEL				1600.00 ✗
E PNT88000 REPLACE AIRCON CONDENSER AND RADIATOR ASSY				120.00 ✗
E PNT98000 SPRAY PAINT BOTH FRONT CHASSIS & BOTH FRONT WHEEL HOUSING				700.00 ✗
S SPECIALISTJOB VACUUM & TOP UP AIRCON GAS				80.00 ✗
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✗
X EXC INSURANCE EXCESS				-600.00
X LAMP ASSY-HEAD,LH	1.00	2210.00	20.00	1768.00 ?
X LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00 ✓
X RESERVOIR & PUMP ASSY-WASHER	1.00	146.00	20.00	116.80 ✓
X PANEL ASSY-HOOD	1.00	1502.00	20.00	1201.60 ✓
X HINGE ASSY-HOOD,RH	1.00	43.00	20.00	34.40 ✓
X HINGE ASSY-HOOD,LH	1.00	43.00	20.00	34.40 ✓
X PANEL-FENDER,LH	1.00	430.00	20.00	344.00 ✓
X PANEL-FENDER,RH	1.00	430.00	20.00	344.00 ✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/12/2020	Cust No/Name	LCV11454/LAI ZHEN NAN (LI ZHENNAN)
	Reg No/Reg Date	SMQ2932D*ECB1/ 07/11/2019
	Date In/Mileage	30/11/2020/ 21108
	Chassis/Package	KNAF5416MK5052954 /KC17
	Engine No	G4FGKH749533
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	02/02/2021/ 09:36	BLK	884 / Lauro Songcuan	25072

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X COVER-FR BUMPER	1.00	633.00	20.00	506.40
X GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40
X GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00
X MOULDING-FRONT BUMPER,RH	1.00	216.00	20.00	172.80
X LAMP ASSY-SIDE REPEATER,RH	1.00	143.00	20.00	114.40
X ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
X AIR DUCT-FR BUMPER,RH	1.00	14.00	20.00	11.20
X BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
X BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
X ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
X COVER ASSY-COWL TOP	1.00	247.00	20.00	197.60
X CLIP-HEAD LAMP MTG	1.00	4.00	20.00	3.20
X LAMP ASSY-FRONT FOG,RH	1.00	303.00	20.00	242.40
X COVER-FR BUMPER FOG LAMP,RH	1.00	15.00	20.00	12.00
X GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.40
X WIRING ASSY-BUMPER EXTENSION	1.00	207.00	20.00	165.60
X CLIP	10.00	2.00	20.00	16.00
X CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00
X GUARD ASSY-FRONT WHEEL,RH	1.00	95.00	20.00	76.00
X RADIATOR ASSY	1.00	646.00	20.00	516.80
X CLEANER ASSY-AIR	1.00	174.00	20.00	139.20
X RETAINER-COWL TOP COVER MTG	6.00	2.00	20.00	9.60
X COOLANT (4L)	1.00	26.00	20.00	20.80
X PANEL ASSY-UNDER COVER	1.00	117.00	20.00	93.60
X CONDENSER ASSY-COOLER	1.00	687.00	20.00	549.60
X TUBE ASSY-SUCTION & LIQUID	1.00	668.00	20.00	534.40
X PULLEY-COOLANT PUMP	1.00	32.00	20.00	25.60
X GASKET-WATER PUMP	1.00	7.00	20.00	5.60
X PUMP ASSY-COOLANT	1.00	174.00	20.00	139.20
X BRACKET ASSY-ENGINE MTG	1.00	208.00	20.00	166.40
X CLIP-HEAD LAMP MTG	1.00	4.00	20.00	3.20
Z TEXT				
OD CLAIM - AIG				

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 02/12/2020	Cust No/Name	LCV11454/LAI ZHEN NAN (LI ZHENNAN)
	Reg No/Reg Date	SMQ2932D*ECB1/ 07/11/2019
	Date In/Mileage	30/11/2020/ 21108
	Chassis/Package	KNAF5416MK5052954 /KC17
	Engine No	G4FGKH749533
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	02/02/2021/ 09:36	BLK	884 / Lauro Songcuan	25072

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
DOA: 29/11/2020 SURVEY: STEVE (LKK) 30/11/2020 17 DAYS				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	10,681.60	Nett	17,291.60
Labour	7,090.00	7% GST on	1210.41
Standard Menu	0.00		
Specialist Job	80.00		
Diagnostics Job	0.00	Total Payable	18,502.01
Sundry/Others	-560.00		
Total(w/o GST)	17,291.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMQ 2932 D

<u>Materials</u>		<u>Cost \$</u>
1	Clip- Head lamp Mtg (2 pcs)	8.00
2	Lamp Assy- Front Fog, RH	303.00
3	Cover- FR Bumper Fog Lamp, RH	15.00
4	Garnish- Radiator Grille	38.00
5	Wiring Assy- Bumper Extension	207.00
6	Clip (10 pcs)	20.00
7	Carrier Assy- Front End Module	675.00
8	Radiator Assy	646.00
9	Cleaner Assy- Air	174.00
10	Retainer- Cowl Top Cover Mtg (6 pcs)	12.00
11	Coolant (4L)	26.00
12	Panel- Under Cover	117.00
13	Condenser Assy- Cooler	687.00
14	Tube Assy- Suction & Liquid	668.00
15	Pulley- Coolant Pump	32.00
16	Gasket- Water Pump	7.00
17	Pump Assy- Coolant	174.00
18	Bracket Assy- Engine Mtg	208.00
		<u>4,017.00</u>
20% Discount		<u>803.40</u>
		<u>3,213.60</u>
<u>Labour</u>		
1	Remove & Install Engine Assy	400.00
2	Repair Both Front Chassis, Both Wheel Housing and Replace Support Panel	1,600.00
3	Replace Aircon Condenser and Radiator Assy	120.00
4	Spray Paint Both Front Chassis & Both Front Wheel Housing	700.00
5	Vacuum & Top Up Aircon gas	80.00
6	To Conduct Computerize Full Wheel Alignment	120.00
		<u>3,020.00</u>
Labour & Materials		6,233.60
7% GST		436.35
Total		<u>6,669.95</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage

CAR NO: SHQ 29320WIP: 25072

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1 /	Clip Headlamp M Ty X2	? (SUPP)	MISSING / OR ✓		
2 /	Headlamp LH	? / SUPP	✓ OR		
3 /	Beam Complete Fr Bumper	? / SUPP	Repair		* Disentk
4 /	Grille Front Bumper	? / SUPP	✓ OR		
5 /	Absorber Front Bumper Energy	? / SUPP	✓ OR		
6 /	Wire Harness Front Bumper	? (SUPP)	✓ TN		
7 /	Air duct Front Bumper RH	? / SUPP	✓ OR		
8 /	Garnish Assy - Radiator Grille upper	? / SUPP	✓ OR		
9 /	Fog lamp RH	? / SUPP	✓ OR	Store 7/10/20	
10 /	Fog lamp cover RH	? / SUPP	✓ OR		
11 /	Cover Cool Top Clip X6	? / SUPP	✓ OR		
12 /	Carrier Front end Module	? / SUPP	✓ OR		
13 /	Carrier Under cover	? / SUPP	✓ OR		
14 /	Coolant	? / SUPP	✓ OR		
15 /	Air cleaner Box Assy	? / SUPP	✓ OR		
16 /	Radiator Assy	? / SUPP	✓ OT		
17 /	Aircon Condenser Assy	? / SUPP	✓ OT		
18 /	Fender shield RH	? / SUPP	✓ CR		
19 /	Bumper Clip X10	? / SUPP	✓ OR		
20 /	Front Bonnet damper	? / SUPP	✓ MIS		

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6SURVEYOR: WU-Steve

CAR NO: SMQ 1932DWIP: 25072

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Remove and install Enging	? / SUPP	MC		
2	Engine Mtg	? / SUPP	(RH) - CRA	Steve 7/12/12	
3	Substion Hosc.	? / SUPP	OT		
4	water pump	? / SUPP	Jammed		
5	water pump Pulley	? / SUPP	OT	Steve 9/12/12	
6	water pump gasket.	? / SUPP	MC		
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Carb 1.6SURVEYOR: Mu-Steve

CAR NO: SMQ 2932DWIP: 25072

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Repair Both Frt wheel housing \$600	? / SUPP	/		
2	Repair Both Frt Body chassis \$600	? / SUPP	/		
3	Rx I radiator condenser \$120	? / SUPP	/	Steve	
4	Top up A/c gas \$80	? / SUPP	/	7/12/20	
5	Replace Support Panel \$400	? / SUPP	/		
6	Wheel Alignment \$120	? / SUPP	/		
7	Rd I Frt Sub Fram for facilitate repair \$400	? / SUPP			
8	Replace all engine components \$200	? / SUPP			
9	Painting Both Frt wheel housing \$350	? / SUPP	/	Steve	7/12/20
10	Painting Both Frt Body chassis \$350	? / SUPP	/		
11		? / SUPP			
12	Add on 07 days - Total 17 days	? / SUPP	/	Steve	7/12/20
13		? / SUPP			
14	Wheel Alignment	? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Corato 1.6SURVEYOR: Mike-Steve