

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5603L**AAD2011-***Not Notarized**Primary Bepain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

01 DEC 2020**SHD5603L**

JTDKB3FU703077154

TOYOTA

PRIUS

AIG

04/12/2018

PART		LIST	
1	COVER, FRONT BUMPER	\$	Bu 516.00 ✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R 716.60
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	R 246.10
1	FRONT BUMPER SIDE RETAINER LH	\$	R 82.30
1	BRACKET, FRONT BUMPER SIDE, LH	\$	R 59.30
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	R 82.30
1	EXTENSION, FRONT BUMPER, LH	\$	R 120.10
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	R 241.90
1	GRILLE, RADIATOR	\$	R 160.50
1	EMBLEM ASSY, RADIATOR GRILLE	\$	R 90.80
1	GRILLE SUB-ASSY, RADIATOR	\$	R 346.00
1	GRILLE, RADIATOR, LOWER NO.1	\$	R 170.10
1	BRACKET, HEADLAMP, LH	\$	R 34.80
1	UNIT ASSY, HEADLAMP, LH	\$	R 2,637.60
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	R 960.50
1	LAMP ASSY, FOG, LH	\$	R 951.40
1	LINER, FRONT FENDER, LH	\$	R 202.50
1	FENDER SUB-ASSY, FRONT LH	\$	R 977.80 ✓
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	R 1,300.70 X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	R 238.30 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	R 926.00 X
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	CM 1,339.30 ✓
TOTAL		\$	8,596.60
25%		\$	2,828.00
		\$	8,484.00

Special Nett

1	FRONT FENDER EMBLEM LH	\$	Me 150.00 ✓
---	------------------------	----	-------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2011-

SHD5603L

- 1 WHEEL RIM COVER
- 1 TYRE 195/65/15
- 1SET FRONT FENDER LINER CLIP
- 1SET ROCKER PANEL MOULDING CLIP
- 1SET FRONT BUMPER CLIP
- 1 FRONT DOOR STICKER

\$	211.50	✓
\$	350.00	X
\$	75.00	X
\$	70.00	X
\$	90.00	66in
\$	100.00	X
TOTAL	\$ 1,046.50	

TOTAL PARTS \$ 9,530.50**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	4001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	301
To check steering geometry and computer wheel alignment	\$	220.00	601
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	5001
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	151
TOTAL	\$	4,380.00	

Over All Total \$ 13,910.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days**10 days****20 days**