

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 01.12.2020
 Emailed : 17.12.2020, 2.55pm
 Date Survey : 03.12.2020

VEHICLE NO : SMQ 8861 K
 MODEL : MIT ATTRAGE 1.2
 WIP : 60266

Material	:	\$	<u>2,271.51</u>
Labour	:	\$	<u>2,230.00</u>
Sub-Total	:	\$	<u>4,501.51</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,501.51</u>
GST 7%	:	\$	<u>315.11</u>
Grand Total	:	\$	<u>4,816.62</u>
Finalise By/Date	:		<u>LOI / 17/12/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 03/12/2020	Cust No/Name	/Mr Pang Chuan Hung (Fang Zhuang)
	Reg No/Reg Date	SMQ8861K / 09/12/2019
	Date In/Mileage	03/12/2020/ 13529
	Chassis/Package	MMBSTA13AKH003362 /DC17P
	Engine No	3A92UJB1635
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/12/2020/ 12:47	BLK	260 / AiTing	60266			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR BODY KIT, REPAIR LH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 450.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR BODY KIT, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPAIR REAR END PANEL LH SIDE → <i>Supp.</i>								225.00
E PNT98000 RESPRAY REAR END PANEL LH SIDE → <i>Supp.</i>								175.00
X	LAMP ASSY, COMB, RR LH				1.00	✓ 335.00	23.00	257.95
X	BRACKET, RR BUMPER, LH				1.00	✓ 28.00	23.00	21.56
X	FACE, RR BUMPER				1.00	✓ 748.00	23.00	575.96
X	BODYKITS				1.00	✓ 1643.00	20.00	1314.40
X	BUZZER, KEYLESS OPERATIO, RR				1.00	91.00	23.00	70.07
X	MUD GUARD, RR LH				1.00	41.00	23.00	31.57
Z TEXT AIG OD CLAIM. DOA : 01.12.20 SURVEYOR STEVE LKK 03.12.20 POLICY NO: 1900256421								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	2,271.51		Nett	4,501.51
Labour	2,170.00	7% GST on	4501.51	315.11
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	4,816.62
Sundry/Others	60.00			
Total(w/o GST)	4,501.51			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMQ 8861 K

<u>Materials</u>		<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	91.00 ✓
2	Mud guard, RR LH	41.00 ✓

Total		132.00
Less 23%		30.36

Total Materials		101.64

<u>Labour</u>		<u>Cost (\$)</u>
1	Repair rear end panel LH side	225.00 ✓
2	Respray rear end panel LH side	175.00 ✓


Total Labour		400.00

Taxable Amount		501.64
7% GST		35.11

Grand total		<u><u>536.75</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

3M08861K.

After erase all DTC,

All DTCs

2020.12.08

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	A13A 2019MY

All DTCs

2020.12.08