

4/12/2020 - STEVE

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0936/2020/NS 4-Dec-20 George Wong 1 of 1 SMV 2946 M AUDI A4 SEDAN 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To dismantle lhs front door panel trim. S/N To dismantle and reinstall lhs wing mirror assy.	\$ 350.00	280
	GRAND TOTAL	\$ 350.00	


For Premium Automobiles Pte Ltd

*Paul
Pai*

08/12/2020

Subject to

insurers approval



Authorised Signature

Carin

4/12/2020

LKK - STEVE

wip: 60659

Kiam/choi

 PREMIUM AUTOMOBILES


55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER / <i>OR</i>		\$ 2,171.00	
2 FRONT BUMPER FIXING PARTS ?		\$ 580.00	
3 FRONT BUMPER SECURING STRIP ?	2	\$ 70.00	
4 FRONT BUMPER GRILLE - CENTRE ?		\$ 194.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X		\$ 208.00	
6 RADIATOR GRILLE / <i>OR</i>		\$ 1,317.00	
7 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>OR</i> 2,1		\$ 268.00	
8 FRONT PARKING AID SENSOR - INNER/OUTER 2		\$ 484.00	
9 FRONT PARKING AID SEAL RING / <i>MC</i> 4		\$ 14.00	
10 FRONT BUMPER WIRING SET ?		\$ 505.00	
11 FRONT BUMPER CARRIER / <i>DO</i>		\$ 795.00	
12 FRONT BUMPER FOAM FILLER PIECE / <i>OR</i>		\$ 123.00	
13 FRONT BUMPER COVER <i>(7p (2) - (24)</i>		\$ 126.00	
14 FRONT BUMPER BRACKET - LH/RH ?	2	\$ 450.00	
15 FRONT BUMPER GUIDE SECTION - LH/RH ?	2	\$ 72.00	
16 CAUTION SIGN STICKER / <i>MC</i>	NEC	\$ 14.00	
17 AIRCON STICKER / <i>MC</i>	NEC	\$ 8.00	
18 LOCK CARRIER BRACKET - LH/RH		\$ 136.00	
19 LOCK CARRIER BRACKET SUPPORT LH/RH <i>Don</i> 2		\$ 56.00	
20 HORN - LH HIGH TONE X		\$ 124.00	
SUB TOTAL SPARE PARTS		\$ 7,715.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 HORN - RH LOW TONE X		\$	124.00
22 SPRING SHACKLE - LH/RH ?	2	\$	58.00
23 BONNET PD		\$	2,763.00
24 BONNET ATTACHMENT PARTS X		\$	408.00
25 BONNET LID HINGE - LH/RH ?	2	\$	602.00
26 BONNET IMPACT PROTECTION - CENTRE CRU		\$	27.00
27 BONNET IMPACT PROTECTION - LH MC		\$	28.00
28 BONNET IMPACT PROTECTION - RH MC		\$	27.00
29 BONNET STRIKER - LH/RH ? X	2	\$	100.00
30 BONNET LID LOCK X	2	\$	424.00
31 BONNET BOWDEN CABLE - CENTRE ?		\$	57.00
32 BONNET BOWDEN CABLE ? ✓ OT		\$	57.00
33 BONNET RELEASE LEVER X		\$	13.00
34 BONNET LID LOCK CABLE X		\$	73.00
35 PLNEUM CHAMBER COVER X		\$	96.00
36 BONNET SOUND ABSORBER X		\$	339.00
37 LED HEADLIGHT - LH/RH - BR	2	\$	15,386.00
38 LIFT CYLINDER - LH/RH ?	2	\$	416.00
39 LIFT CYLINDER CORRUGATED PIPE ?		\$	92.00
40 LOCK CARRIER ? CR		\$	1,004.00
SUB TOTAL SPARE PARTS	:	\$	22,094.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 COOLANT REGULATOR SUPPORT ?	2	\$	75.00	
42 AIRCON CONDENSER DO		\$	615.00	
43 REFRIGERANT LINE PRESSURE SENDER ?		\$	181.00	
44 HIGH PRESSURE SWITCH VALVE ?		\$	49.00	
45 REFRIGERANT LINE ?		\$	245.00	
46 TEMPERATURE SENSOR BRACKET ?		\$	18.00	
47 EXTERNAL TEMPERATURE SENSOR ?		\$	56.00	
48 CHARGE AIR COOLER ?		\$	580.00	
49 RADIATOR ?		\$	837.00	
50 READY MIX COOLANT ?		\$	177.00	
51 RADIATOR FAN RING ?		\$	242.00	
52 RADIATOR FAN ?		\$	1,896.00	
53 RADIATOR AIR GUIDE - LH/RH OUTER ?	2	\$	56.00	
54 RADIATOR AIR GUIDE - LH/RH INNER ?	2	\$	24.00	
55 RADIATOR AIR GUIDE - UPPER ?		\$	16.00	
56 RADIATOR AIR GUIDE - LOWER ?		\$	22.00	
57 AIR INTAKE AIR DUCT - RH ?		\$	22.00	
58 AIR INTAKE AIR GUIDE ?		\$	53.00	
59 AIR INTAKE HOSE ?		\$	94.00	
60 AIR MASS METER ?		\$	551.00	
SUB TOTAL SPARE PARTS		\$	5,809.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
61 FRONT DOOR - LH X R		\$	2,354.00	
62 FRONT DOOR OUTER SEAL - LH X	NEC	\$	203.00	
63 BONDING AGENT X	NEC	\$	47.00	
64 CLEANING SOLUTION X	NEC	\$	65.00	
65 FRONT DOOR ATTACHMENT PARTS X		\$	870.00	
66 FRONT DOOR CATCH X		\$	104.00	
67 WINDOW SLOT SEAL LH/RH X CAT (2) 21		\$	606.00	
68 WINDOW GUIDE TRIM STRIP - LH/RH X	2	\$	508.00	
69 FRONT NO PLATE RT	S/N	\$	60.00	
70 SUNDRIES ?		\$	400.00	
TOTAL SPARE PARTS	:	\$	40,835.00	
TOTAL LABOUR CHARGES	:	\$	15,894.00	
GRAND TOTAL	:	\$	56,729.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.