

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHC1330E
 Make : TOYOTA
 Model : PRIUS
 DOA : 31.08.2020

Date :
 Insurance: CHINA
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
1	REAR TRUNK LID COVER			\$1,126.60
1	REAR TRUNK LID GLASS W/MOULDING			\$1,778.30
1	REAR TRUNK LID GLASS BLACK.			\$1,569.70
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90
1	REAR BUMPER			\$458.60
1	REAR BUMPER UNDER COVER			\$552.60
1	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
1	REAR BUMPER UNDER COVER CENTRE			\$232.00
1	REAR BUMPER TOWING COVER			\$82.70
1	REAR BUMPER REINFORCEMENT STAY LH/RH		\$139.60	\$279.20
1	TAIL LAMP RH UPPER			\$557.90
1	TAIL LAMP RH LOWER			\$548.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER REINFORCEMENT			\$318.80
	SUB TOTAL			\$8,808.00
	LESS 25%			\$2,202.00
	DISCOUNTED TOTAL			\$6,606.00
1	REAR BUMPER MAT			\$50.00
1	REAR NUMBER PLATE W/HOLDER			\$55.00
1	REAR TRUNK LID APPS STICKER			\$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
				\$340.70
	NETT			
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$90.00
	Tuff Kote			\$120.00
	Remove/Refix Reverse Sensor			\$90.00
	TOTAL LABOUR			\$1,700.00
	ESTIMATE TOTAL			\$8,646.70

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 1779 5749
 WP 1/12/2020 Spm
 Lumpur
 Resurvey after repair 04 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Gey Road Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 7687

Date/Time: 01.12.2020 14:30

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305436694

STOMER
COMFORT TRANSPORTATION PTE LTD
/MS 7010045
STOMER NO 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755
.. (R) (O)
(P)


REGN NO: SHC1330E	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)30	DATE/TIME IN 11.2020 10:50
YR OF MANU. 19.07.2017	TARGET DATE
CHASSIS CODE JTDKB3FU903560564	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 30.11.2020
NATURE: 3P 30.11.2020

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHC1330E CHIANG

Vehicle No.: SHC1330E

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard