

ASS. REC. BY:

REF:

M/20013304/KT

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$24,598k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 98044

Yr Regn:

04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perad Latitude

c.c

1995

Colour

M. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

577682

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1 ABL15AUC 277326

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order /

Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

NI / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailon

Front

Rear

R/Bal.

P

mm

R/Bal.

6

mm

L/Bal.

P

mm

L/Bal.

6

mm

D.O.A.

28/11/20

D.O.I.

2/12/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA not ready

4/12

L1Png @ 1750. Cabin (Red: 5602.75, 76%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S + R.S. SI

Fees

Others

Report Format:

Lump Sum / I.B.I. (\$

1750

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y**AAD2012-***Not Authorised*
61 Sep & 1730h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9804Y

VF1ABL15AUC277326

RENAULT

LATITUDE

*28.11.2020**TCW*

14/04/2014

02 OCT 2020**PART**

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 HEADLAMP RH
- 1 FENDER PANEL FRT RH
- 1 FENDER BRACKET FRT RH
- 1 WHEELARCH FRT RH
- 1 WIPER RESERVOIR

LIST	
\$ <i>Buckm</i>	747.20 ✓
\$ <i>Sn</i>	344.70 X
\$ <i>Dr</i>	101.40 ✓
\$ <i>Sn</i>	207.21 X
\$ <i>mym</i>	743.60 ✓
\$ <i>n</i>	437.10 X
\$ <i>Sn</i>	106.40 X
\$ <i>Sn</i>	191.40 X
\$ <i>Sn</i>	179.60 X

TOTAL	\$	3,058.61
10%	\$	305.86
	\$	2,752.75

Special Nett

- 1 BUMPER CLIP FRT
- 1 BUMPER RETAINER CLIP FRT
- 1 WHEELARCH CLIP FRT
- 1 TYRE
- 1 TYRE RIM
- 1 FENDER SCREW

\$ <i>nee</i>	90.00 <i>66sn</i>
\$ <i>na</i>	75.00 X
\$ <i>na</i>	75.00 X
\$ <i>Sn</i>	300.00 X
\$ <i>Sn</i>	350.00 X
\$ <i>nn</i>	60.00 X

TOTAL	\$	240.00
--------------	----	---------------

TOTAL PARTS	\$	2,992.75
--------------------	----	-----------------

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2012-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9804Y

To rust-proofing and apply undercoat of the affected areas.	\$	nn	230.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$		170.00	X
Putty and spray painting of the affected portion.	\$		1,400.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
TOTAL	\$		4,360.00	
Over All Total	\$		7,352.75	

(LUMP SUM) Repair Days**20 Days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD9804Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Dec 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001064
Chassis No.:	VF1ABL15AUC277326
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Apr 2014
First Registration Date:	14 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2022
PARF Rebate Amount:	\$8,123.00
Intended COE Rebate Details	
COE Expiry Date:	13 Apr 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$59,871.00
COE Rebate Amount:	\$10,207.00
Total Rebate Amount:	\$18,330.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Dec 2020

OK