

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Nov 004/2020
Date	30/11/2020
Vehicle No	GBC497K
Make / Model	Volkswagen Caddy

To: AXA Insurance Singapore Pte Ltd
Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

WV1222K ZBX254810

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>Dented</i>		\$ 780.00 ✓
1 set	rear bumper clip <i>me</i>		\$ 50.00 ✓ 30
1 pc	rear number plate <i>Best</i>		\$ 60.00 ✓
1 pc	70 KM/H sticker <i>me</i>		\$ 15.00 ✓
1 pc	rear end panel <i>Dented</i>		\$ 480.00 ✓ 1890
1 pc	o/s rear door <i>Dented</i>		\$ 2,380.00 ✓ 1890
1 pc	n/s rear door <i>Dented</i>		\$ 2,780.00 ✓
1 pc	n/s rear door outer handle <i>Dented</i>		\$ 380.00 ✓
1 pc	o/s rear bumper side retainer <i>3mm</i>		\$ 68.00 ✓
1 pc	n/s rear bumper side retainer		\$ 68.00 ✓
1 pc	o/s rear door inner lock <i>new Dented</i>		\$ 612.00 ✓ 305
1 pc	n/s rear door inner lock <i>Dented</i>		\$ 612.00 ✓ 305
1 pc	o/s rear door glass sealant <i>3mm</i>		\$ 80.00 ✓ 60
1 pc	n/s rear door glass sealant <i>3mm</i>		\$ 80.00 ✓ 60
1 pc	n/s rear door fender sealant <i>new</i>		\$ 80.00 ✓
1 set	reverse sensor <i>Dented</i>		\$ 200.00 ✓
1 pc	n/s rear fender <i>Repair</i>		\$ 1,985.00 ✓
2 pcs	o/s rear door hinge <i>new</i>	\$ 192.00	\$ 384.00 ✓
2 pcs	n/s rear door hinge <i>lower Bar</i>	\$ 192.00	\$ 384.00 ✓ 192
1 pc	caddy emblem <i>me</i>		\$ 79.00 ✓
1 pc	rear bumper reinforcement <i>Best</i>		\$ 820.00 ✓ 682
1 pc	n/s tail lamp <i>Crushed</i>		\$ 385.00 ✓
1 pc	rear wiper motor <i>new Dented</i>		\$ 975.00 ✓ 375
1 pc	rear exhaust pipe <i>new</i>		\$ 1,850.00 ✓
1 pc	bumper tow hook cover <i>new</i>		\$ 35.00 ✓
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,200.00 ✓ 1000
2	to putty and spray painting on affected area		\$ 1,400.00 ✓ 200
3	anti rust		\$ 140.00 ✓ 60
4	wiring check		\$ 80.00 ✓ 30
5	R&R reverse sensor		\$ 30.00 ✓
6	R&R left rear fender glass sealant		\$ 180.00 ✓
7	R&R left rear door windscreen		\$ 180.00 ✓ 80
8	R&R right rear door windscreen		\$ 180.00 ✓ 80
9	R&R fuel tank		\$ 120.00 ✓
	<i>Red R upholstery</i>		\$ 150.00 ✓ 80
	Subtotal:		\$ 18,472.00

8K

Total: 10033.60
L/S: 78K
L/S 03/12/20
07

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature