



INDIA INTERNATIONAL INSURANCE  
64 Cecil Street #04, #05  
IOB Building  
Singapore 049711  
Attn: Motor Claims Dept

Your Ref: SHD4652B  
Our Ref: DS/2354607/SLN2953X

**"Without Prejudice"**

Date: 11 March 2021

Subject: **ACCIDENT INVOLVING VEHICLES SLN2953X & SHD4652B ON 29/11/20**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair: \$ 26,678.02	Excess	: \$ -
Loss of Use : \$ 2,400.00 (\$100*24 days)	GIA/LTA Search	: \$ -
Loss of Rental: \$ -	Others	: \$ 10.70
	<b>Total</b>	<b>: \$ 29,088.72</b>

A copy of each of the following supporting documents is enclosed:

1. Copy of Final Repair Bill
2. STA Inspection Receipt, LTA letter dated 22.12.2020
3. Original Letter of Authorisation
4. Certificate of Insurance

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)  
[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel Aftersales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel Aftersales  
6319 0527  
Fax 6479 6624

280  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel Aftersales  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Evelyn Chan / Mr Suhaimi at 6319-0175 / Fax. 6479-4601 or email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Yours sincerely

  
Cresendo Lagman  
Customer Service Manager, Body & Paint

  
Bernard Wan  
Service Manager – Body & Paint

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLN 2953 X & SHD 4652 B ON 29/11/2020.

I, Tan Teck Ching owner of Vehicle Registration No. SLN 2953 X  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment  
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

Name: Tan Teck Ching (Date) 30/11/2020  
NRIC No.: 581344164

In the presence of:



Name: Tan (Date) 30/11/2020  
NRIC No.: 011266

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT20110505  
Claimant Ref: SLN 2953X

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 26,678.02 (repair cost), S\$ 1,020.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLN 2953X that was damaged pursuant to the accident which occurred on 29/11/2020 (date) at TWDS TUAS BEF CLEMENTI RD (location) involving vehicle no. SHD 4652B (insured vehicle). This is pursuant to the inspection conducted on 01/12/2020 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN TECK CHING ("the third party claimant") of vehicle no. SLN 2953X to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLN 2953X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 27,698.02 to PERFORMANCE MOTORS LIMITED.

Dated this 01 day of June 20 21

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

PERFORMANCE MOTORS LIMITED

303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 6319 0100 (Sales)  
6319 0111 (After sales)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

This settlement does not preclude/prejudice the Claimant/Driver/Passenger for personal injury at a later date should such a claim arises.



303, Alexandra Road  
Sime Darby Performance  
Singapore 159941  
Tel. 63190100 (Sale)  
63190111 (After)  
Fax. 64747770280, Kampong Arang  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (Aft)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Tel. 63190528  
63190533/530  
Fax. 64796601  
64796672

## SERVICE TAX INVOICE

Repair Order No. : B1 1513693

Date IN : 08/12/2020

Motor Claim Advisor: Chua Kee Sin

Page No. : 1 of 3

Invoice Number : 2354607 / WSB

Invoice Date : 09/03/2021

Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

## - CUSTOMER INFORMATION -

Mr Tan Teck Ching (Chen Dixin)  
311C Clementi Avenue 4  
#14-191

Singapore 123311

## - INVOICE TO - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216D G TOURER	22031

## - - - L A B O U R 1 - - -

	Retail Price	DISC%	NETT
Rplace rear floor pan,tail end panel,boot lid,rear bumper include removing attachment, and repair on the accident damage area	6,800.00	0.00	6,800.00
Spray painting rear floor pan, tail end panel,both rear side fender,rear boot lid and rear bumper	4,470.00	0.00	4,470.00
To transfer rear windscreen glass to new boot lid.	676.00	0.00	676.00
To conduct water leak tests.	75.00	0.00	75.00
To check electrical wiring sys tem and lighting at the rear section.	150.00	0.00	150.00
To replace rear exhaust silencer including alignment system.	451.00	0.00	451.00
To carry out body cavitypreservation. (For cut panel).	451.00	0.00	451.00
To carry out body cavitypreservation. (Per panel).	100.00	0.00	100.00
To replace front centre exhaust silencer including alignment.	451.00	0.00	451.00
To remove and install boot compartment carpet and garnish to facilitate repair.	230.00	0.00	230.00
To tow accident vehicle to PML workshop.	150.00	0.00	150.00
Being charge for LTA inspection fees.of breaking and install no plate seal	160.00	0.00	160.00
Sundries	150.00	0.00	150.00
To mount vehicle on celette bench to facilitates re-alignment of body/chassis according to BMW specification	2,950.00	0.00	2,950.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00	0.00	0.00
DATE OF ACCIDENT :29.11.2020. 3RD PARTY CAR :SHD4652B.			
YOUR REF NO :INDIA INT,L			
VEHICLE WAS SURVEYED BY RASUL FROM LKK AUTO ON 01.12.2020@1120HRS. AUTHORISED BY CECILIA CHONG FROM LKK VIA EMAIL ON 08.12.2020.			
PROPOSE LOSS OF USE = \$100X24 THE AMOUNT IS SUBJECTED TO	0.00	0.00	0.00
INSURANCE COMPANY CONFIRMATION.			
TO BREAK SEAL AND INSTALL SEAL RECEIPT NUMBER CPO200003414660	21.40	0.00	21.40
AND CPO020003397589 \$21.40			

303, Alexandra Road  
Sime Darby Performance  
Singapore 159941  
Tel. 63190100 (Sale)  
63190111 (Aft)  
Fax. 64747770280, Kampong Arang  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (Aft)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Tel. 63190528  
63190533/530  
Fax. 64796601  
64796672

## SERVICE TAX INVOICE

Repair Order No. : B1 1513693

Date IN : 08/12/2020

Motor Claim Advisor: Chua Kee Sin

Page No. : 2 of 3

Invoice Number : 2354607 / WSB

Invoice Date : 09/03/2021

Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

Total Labour 1: 17,285.40

P A R T S				Retail		DISC%	NETT
	Qty	Price					
BOOTLID	1	1,210.35	3.00				1,174.04
REAR BUMPER CARRIER	1	460.40	3.00				446.59
REAR BUMPER TRIM STRIP (CHROM)	1	110.55	0.00				110.55
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,045.45	0.00				1,045.45
LETTERING 216 D	1	64.45	0.00				64.45
GROMMET	2	0.80	0.00				1.60
PLAQUE 74MM	1	71.60	0.00				71.60
REAR RH REFLECTOR	1	38.85	0.00				38.85
TAIL PANEL	1	357.00	0.00				357.00
INTERIOR TAIL TRIM	1	280.50	0.00				280.50
SUPPORT	1	45.55	0.00				45.55
RR BUMPER LH INNER SIDE GUIDE	1	61.35	0.00				61.35
RR BUMPER RH INNER SIDE GUIDE	1	61.35	0.00				61.35
3rd ROW LUGGAGE COMPARTMENT TRAY	1	126.90	0.00				126.90
THERMAL PROTECTION LUGGAGE COMP. WE	1	58.30	0.00				58.30
TRUNK FLOOR	1	530.55	0.00				530.55
(DG/SL) SOUND DEADENER 1160X700MM	1	83.65	0.00				83.65
COARSE THREADED BOLT (L=14.2MM)	10	2.65	0.00				26.50
PUNCH RIVET N4	20	0.55	0.00				11.00
BLIND RIVET AVIBVLB	20	0.55	0.00				11.00
(DG/SL) BODY ADHESIVE K5B (195ML)	1	336.75	0.00				336.75
(DG) CLEANER R1 (100ML)	1	26.15	0.00				26.15
SCREW (SF PLUS M5X15)	3	0.55	0.00				1.65
(DG) BODYWORK ADHESIVE K5A (50ML)	1	116.15	0.00				116.15
(S/L) SEAM SEAL 300ML	1	33.80	0.00				33.80
LOADING SILL COVER (ANTHRAZIT)	1	79.55	0.00				79.55
SNAP LOCKING COUPLING	3	1.05	0.00				3.15
EXPANDING NUT	2	1.00	0.00				2.00
HOLDER EXHAUST SYSTEM	1	28.75	0.00				28.75
CLAMPING BUSH	1	54.60	0.00				54.60
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	0.00				263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	1	27.85	0.00				27.85
(DG) CLEANER R1 (100ML)	1	26.15	0.00				26.15
REAR SILENCER	1	1,015.05	0.00				1,015.05
FRONT SILENCER	1	1,025.85	0.00				1,025.85

Total Parts : 7,647.33



303, Alexandra Road  
Sime Darby Performa  
Singapore 159941  
Tel. 63190100 (Sale)  
63190111 (Aft)  
Fax. 64747770

280, Kampong Arang  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (Aft)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Tel. 63190528  
63190533/530  
Fax. 64796601  
64796674

**SERVICE TAX INVOICE**Repair Order No. : **B1 1513693**Date IN : **08/12/2020**Motor Claim Advisor: **Chua Kee Sin**Page No. : **3 of 3**Invoice Number : **2354607 / WSB**Invoice Date : **09/03/2021**Payment Terms : **30 Days From Invoice**Invoice By : **Mahamod Bin Mohd Sanif**

Labour Charges :	<b>16,954.00</b>	Total Labour & Parts Charges :	<b>S\$ 24,932.73</b>
Parts Charges :	<b>7,647.33</b>	Less Insurance Excess :	<b>S\$ 0.00</b>
Lubricant/Misc :	<b>331.40</b>	Invoice Total Amount Exclude GST :	<b>S\$ 24,932.73</b>
		GST @ 7% :	<b>S\$ 1,745.29</b>
		Invoice Total Amount Include GST :	<b>S\$ 26,678.02</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 26,678.02**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



STA Inspection Pte Ltd  
302 Sin Ming Rd  
Singapore 575627  
Tel: 64521398

\*\*\*Duplicate Copy\*\*\*  
\*\*\* RECEIPT \*\*\*

CO REG NO : 198204973D  
GST REG NO : M2-0058358-2  
22-Dec-2020 9:15 am

Receipt No. : CPO20003397589  
Cashier : 60720225  
Machine : CPO2  
Cust Code : CASH  
Customer : Walk-In  
Vehicle No. : SLN2953X

Item	Amount
S-PIN	10.00
GST	0.70
Amount Due	10.70
CASH	10.70
TENDER	10.70
ROUNDING DIFF	0.00

\*\*\*THANK YOU\*\*\*  
STRICTLY NO REFUND

STA Inspection Pte Ltd  
302 Sin Ming Rd  
Singapore 575627  
Tel: 64521398

\*\*\* RECEIPT \*\*\*

CO REG NO : 198204973D  
GST REG NO : M2-0058358-2  
15-Jan-2021 2:25 pm

Receipt No. : CPO20003414860  
Cashier : 60720225  
Machine : CPO2  
Cust Code : CASH  
Customer : Walk-In  
Vehicle No. : SLN2953X  
Chassis NO. :  
WBAZE320605H46190  
Front Seal No :  
Rear Seal No : 246862

Item	Amount
SB2	10.00
GST	0.70
Amount Due	10.70
CASH	10.70
TENDER	10.70
ROUNDING DIFF	0.00

\*\*\*THANK YOU\*\*\*  
STRICTLY NO REFUND

10 Sin Ming Drive Singapore 575701

www.lta.gov.sg

22 Dec 2020

Our ref 2212200104N002017877

TAN TECK CHING (CHEN DIXIN)  
APT BLK 311C CLEMENTI AVENUE 4  
#14-191  
SINGAPORE 123311

Dear Sir/Madam

**APPROVAL TO BREAK AND RESEAL NUMBER PLATE(S) OF REVISED OFF-PEAK  
CAR: SLN2953X**

We refer to your application to break and reseal the number plate(s) for the above-mentioned vehicle.

2. Your application has been approved and you may proceed to remove the **rear** number plate(s) of the vehicle. Once the repair work or any other work on the vehicle is completed, you are required to refit the bracket(s) and number plate(s) and send the vehicle to any of the following vehicle inspection centres for inspection and sealing of the number plate(s) by **21 Jan 2021**:

- STA Inspection Pte Ltd
- JIC Inspection Services Pte Ltd
- VICOM Ltd

3. Please ensure that the number plate(s) is/are resealed by the date stated above. You are required to submit a fresh application with justifications and supporting documents (if any) to our office at LTA, 10 Sin Ming Drive, Singapore 575701, VRL Service Operations Division at least 1 working day before **21 Jan 2021** if you need more time to complete the work on the vehicle.

4. Please be advised that prior approval from the LTA must be obtained before breaking the seal and resealing the number plate(s) of the vehicle. It is a serious offence for any person, except a person authorised by the Registrar of Vehicles, to remove, break or tamper with a seal affixed on a vehicle without our prior approval. Any person convicted of the offence shall be liable with a fine not exceeding \$1,000 or imprisonment to a term not exceeding 3 months, and for the second or subsequent offences a fine not exceeding \$2,000 or imprisonment to a term not exceeding 6 months.





## NUMBER PLATE SEALS INSPECTION CERTIFICATE

Serial No. S20210115001

Vehicle No. : SLN2953X	Make & Model : B.M.W. 216D GRAN TOURER LED NAV 7 SEATER
Seal No (Front) : 224275	Seal No (Rear) : 246862
Type of Inspection : REPLACEMENT	Chassis No. : WBA2E320605H46190

Inspection Items

Legend: P-Pass F-Fail NA-Not Applicable

Front Seal		Status	Rear Seal		Status
1	Number Plate	P	1	Number Plate	P
2	Bolt & Nut	P	2	Bolt & Nut	P
3	Brackets	P	3	Brackets	NA
4	Seal	P	4	Seal	P

**RESULT**

**PASS**

Remarks

REPLACEMENT SEAL (REAR) .

This is to certify that the number plates of the above motor vehicle were examined and found to comply with the prescribed statutory requirements.

The number plates were duly sealed.

Inspected By:

60720167

Chin Bee Teck

Date & Time Issued

15/01/2021

14:39

This is a computer-generated document. No signature is required.

For the purpose of renewing road tax, this Certificate must be presented within 3 months from the date of issue.

# Print Received Message

This mail is associated with :

**\*SLN2953X (MCT20110505)**

**[SHD4652B]**

TP

TAN TECK CHING

Nov 29 2020 7:00PM

[-]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 21/05/2021 10:42 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$27708.72) - SLN2953X - Claim Handler: Sherini Pillai

Approved:27708.72.