



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Ref: CS/AGI20013395/Uqd3q2 Date: 05/01/2021 | Code: AGI |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SGW 3830Y | Veh. Inspected | SLQ 1647X | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | C10008203/CH | Excess (\$) | 0.00 | |
| Assign From | IVY RATILLA | Assign Date | 04/12/2020 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MITSUBISHI LANCER (A) | c.c | 1590 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | JMYSRCY1AGU006841 | Colour | BLUE | |
| Odometer | 78261 KM | Steering | AFFECTED | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/60 R16 | DUNLOP | 6 mm | |
| L/H Front Tyre | 205/60 R16 | DUNLOP | 6 mm | |
| R/H Rear Tyre | 205/60 R16 | DUNLOP | 6 mm | |
| L/H Rear Tyre | 205/60 R16 | DUNLOP | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 01/12/2020 | Inspection Date | 04/12/2020 | |
| Survey held at | QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |