



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	KCV12535/WEE SIEW KHENG SMQ9160T / 10/12/201 / 2971 MMBSTA13AKH003639 3A92UJC3543 MIT/19MY ATTRAGE 1.2 CVT U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	05/12/2020/ 12:01	QUD	247 / DonBong	60401				3150.00
Description of Goods / Services									
E PNT88000									240.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER, REAR BODY KIT, CUT/WELD RH REAR FENDER, REAR END PANEL 450 X S									
E PNT88000									80.00
REMOVE AND INSTALL REAR WINDSCREEN GLASS									
M SUNDRY									120.00
SUPPLY REAR WINDSCREEN SEALANT (photo)									
E PNT88000									60.00
REMOVE AND INSTALL REAR CABIN AND OTHERS ATTACHMENT TO FACILITATE REPAIR WOPK									
E PNT88000									2450.00
REMOVE AND INSTALL PARKING SENSOR									
E PNT98000									80.00
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER, REAR BODY KIT, REAR BOOT LID, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION 1750									
M SUNDRY									50.00
APPLICATION LAT FOR BREAK SEAL AND RESEAL REAR OPC NUMBER PLATE									
M SUNDRY									40.00
SUPPLY REAR NUMBER PLATE WITH FRAME									
M SUNDRY									120.00
SUPPLY C&C LOGO 80									
M SUNDRY									30.00
APPLY BODY SEALANT									
A 54900099									80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									
M SUNDRY									120.00
PERFORM RUST PREVENTION									
A 10028901									50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST 20									
M SUNDRY									587.51
SUNDRIES									
M PANEL,QTR,OTR RH						1.00	763.00	23.00	

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12535/WEE SIEW KHENG Reg No/Reg Date SMQ9160T / 10/12/201 Date In/Mileage / 2971 Chassis No MMBSTA13AKH003639 Engine No 3A92UJC3543 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	05/12/2020/ 12:01	QUD	247 / DonBong	60401

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL, RR COMB LAMP HSG, RH	1.00	60.00	23.00	46.20
M EXTN, QTR PANEL, UPR OTR RH	1.00	118.00	23.00	90.86
M LAMP ASSY, COMB, RR RH	1.00	335.00	23.00	257.95
M GROMMET, TAIL LAMP	2.00	3.00	23.00	4.62
M GROMMET, TAIL LAMP	2.00	3.00	23.00	4.62
M PANEL, TRUNK LID	1.00	791.00	23.00	609.07
M HINGE, TRUNK LID, LH	1.00	203.00	23.00	156.31
M HINGE, TRUNK LID, RH	1.00	203.00	23.00	156.31
M WEATHERSTRIP, TRUNK LID	1.00	157.00	23.00	120.89
M LATCH, TRUNK LID	1.00	218.00	23.00	167.86
M STRIKER, TRUNK LID LATCH	1.00	20.00	23.00	15.40
M MARK, ATTRAGE	1.00	21.00	23.00	16.17
M MARK, THREE-DIA	1.00	69.00	23.00	53.13
M GARNISH, RR END PANEL	1.00	336.00	23.00	258.72
M PANEL, RR END	1.00	425.00	23.00	327.25
M TRIM, RR END	1.00	66.00	23.00	50.82
M BRACKET, RR BUMPER, LH	1.00	28.00	23.00	21.56
M BRACKET, RR BUMPER, RH	1.00	28.00	23.00	21.56
M CLIP, RR BUMPER	8.00	4.00	23.00	24.64
M FACE, RR BUMPER	1.00	748.00	23.00	575.96
M BODY KIT ATTRAGE	1.00	1643.00	00.00	1643.00
M STOPPER, WINDSHIELD GLASS	2.00	3.00	23.00	4.62
M SPACER, RR WINDOW	3.00	9.00	23.00	20.79

Estimate

SURVEYOR NAME: Steve CLKK
 SURVEYOR SIGNATURE: OD - NH Aut
 DATE: Excess ?
 REMARKS: P/P
By Bel Sy

KKK Auto Consultants hereby notify
 Confirmed & accepted by:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 Authorized signatory and company stamp

12 days	Nett	11,905.82
7/12/20, 12:00 pm	7% GST on	833.41
	Total Payable	12,739.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimate is quoted excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.