

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747-6720 REG NO 200501102H

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • The only survey is on a "Without Prejudice" basis
 • No legal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 08.12.2020
 VEH NO : SJM7039G
 MODEL : Suzuki Grand Vitara
 D O A : 29.11.2020
 YR REF : SDL7733L

Xiao Tony

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJM7039G (SUZUKI GRAND VITARA)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Door - RH <i>Rpr</i>	1	795.65 <i>x</i>
2	Rear Door Lower Protector - RH <i>new</i>	1	293.15 <i>x</i>
			1,088.80
	Less 10%		(108.88)
			\$ 979.92
	Total Parts		\$ 979.92

LABOUR CHARGE

1	To knocking & pull out rear door (RH) & renew above parts	\$	200.00 <i>50.</i>
2	To putty & spray up paint works <i>650</i>	\$	800.00 <i>600.</i>
3	To transfer door fittings	\$	150.00 <i>x</i>
	Total Labour	\$	1,150.00
	Grand Total	\$	2,129.92

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 650
(P/P)
03 Days