

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AIG ASIA PACIFIC	INSURANCE PTE LTD	F	Ref:	CS3/AIG20008471/Qvf3e2-1	
	78 SHENTON WAY AIG BUILDING SINGAPORE 0791		С	Date:	14/12/2020	
	ATTN : ANGIE GA	N GEOK LING	(	Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBF 1687G	Veh. Inspected		SFV 5688X	
	Policy No.	2100474873	Coverage (\$)		0.00	
	Claim No.	3191468512SG	Excess (\$)		0.00	
	Assign From	ANGIE GAN GEOK LING	Assign Date		07/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	SUZUKI SWIFT SPORT M	c.c		1586	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	JSAFZC32S00100727	Colour		SILVER	
	Odometer	269712 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/40 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	215/40 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	215/40 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	215/40 R17	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/08/2020	Inspection Date		17/08/2020	
	Survey held at	A-TEC MOTORZ PTE LTD				
		39 WOODLAND CLOSE #02-43 MEGA @WOODLAND SINGAPORE 737856				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					