

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

07 DEC 2020

ESTIMATE

Estimate No. : b1 56780
Date Estimated : 07/12/2020
Prepared By : Brandon Chan Eng Meng

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ng Pei Ling Sherona (Huang Peiling)
25 Chee Hoon Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 299754

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGN980P	WBAYE22010DZ21047	19/02/2014	730LiA	0

DESCRIPTION

To replace front LH fender, front LH door & all attachment items casue by accident.

1700 ~~2,550.00~~

To spray paint front LH fender ,front LH door.

1593 ~~1770.00~~

To check electrical wiring sys tem at the front section for p roper function.

150 ~~177.00~~

To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (1 door).

451 ~~531.00~~

To carry out body cavitypreser vation. (Per panel).

100 ~~118.00~~

Sundries

? 150.00

Total Labour 1: 5,296.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH DOOR <i>bt</i>	1	2,229.20	2,229.20
FRT LH FENDER <i>bt</i>	1	1,236.65	1,236.65
LH TRIM ELEMENT <i>?</i>	1	78.85	78.85
LH OUTSIDE MIRROR W/OUT GLASS <i>sc</i>	1	1,490.95	1,490.95
LH MIRROR COVER PRIMED <i>repy</i>	1	142.75	142.75
(S/L) FRT DOOR WEATHERSTRIP	1	226.25	226.25
FRT LH DOOR ROOF SEAM SEAL <i>?</i>	1	152.40	152.40
(S/L) FRT LH DOOR A JOINT GASKET <i>?</i>	1	94.20	94.20

Total Parts : 5,651.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56780

Page No. : 2 of 5

Date Estimated : 07/12/2020

Prepared By : Brandon Chen Eng Meng

REGN. NO.	CHASSIS NO.	ENTRY DATE	MODEL	MILEAGE
SGN980P	WBAYE22010DZ21047	15/02/2014	730LiA	0

Claims OD (Ord Part) / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 08/12/2020 091410 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010061 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail rasul@kkkauto.com

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,296.00
Parts	:	5,651.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	766.31
Grand Total	:	<u>11,713.56</u>

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **