

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Dec 2020

Preliminary Advice

Insured Vehicle No	: GBK1369Z	Accident Date	: 04/12/2020
TP Vehicle No	: SHC5895R	Assignment Date	: 07/12/2020
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 14
Date of Inspection	: 10/12/2020		
Inspection At	: TRANSCAB (HQ) NO 2 AMK STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,379.69
Revised Amount	:S\$	15,674.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,674.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :