

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 07/12/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLM6079Z

CHASSIS NO : RU31217198

MAKE / MODEL : Honda Vezel Hybrid 1.5X CVT

DATE OF ACCIDENT : 06/12/2020

YOUR INSURED VEHICLE NUMBER :SML 8837H

MILEAGE : 256690 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear tailgate / PB	1PC	\$ 1,450.00	\$ 1,450.00	953
2	Rear tailgate back door trim board 2 CRU	1PC	\$ 580.00	\$ 580.00	320-5
3	Rear tailgate Vezel emblem X NR	1PC	\$ 86.80	\$ 86.80	✓
4	Rear tailgate Honda emblem X SVC	1PC	\$ 81.30	\$ 81.30	X
5	Rear tailgate HYBRID emblem / NRc	1PC	\$ 84.00	\$ 84.00	✓
6	Rear tailgate windscreen moulding / NRc	1PC	\$ 195.00	\$ 195.00	140.00
7	Rear tailgate weatherstrip 2 CRU	1PC	\$ 155.00	\$ 155.00	✓
8	Rear tailgate lock / Jam	1PC	\$ 550.00	\$ 550.00	230.00
9	Rear tailgate lock catch X SVC	1PC	\$ 180.00	\$ 180.00	X
10	Rear RH tail lamp X SVC	1PC	\$ 780.00	\$ 780.00	X
11	Rear RH taillamp reflector X SVC	1PC	\$ 480.00	\$ 480.00	X
12	Rear LH taillamp 2 CRU	1PC	\$ 780.00	\$ 780.00	460-50
13	Rear LH taillamp refelector / CRU	1PC	\$ 480.00	\$ 480.00	380.00
14	Rear end panel 2 PB	1PC	\$ 830.00	\$ 830.00	530.00
15	Rear end panel top garnish X SVC	1PC	\$ 155.00	\$ 155.00	X
16	Rear bumper / CRU	1PC	\$ 955.00	\$ 955.00	549.00
17	Rear bumper RH reflector X SVC	1PC	\$ 180.00	\$ 180.00	X
18	Rear bumper LH reflector X M/S	1PC	\$ 180.00	\$ 180.00	150.00
LIST TOTAL S\$:				\$ 8,182.10	
20.00% DISCOUNT S\$:				\$ 1,636.42	
Total				\$ 6,545.68	

SPECIAL NETT

1	Rear bumper clips	1 SET	\$ 80.00	30 ✓
2	End panel top garnish clips	1 SET	\$ 80.00	
3	Reverse sensor	1PC	\$ 250.00	200 ✓
4	Body sealant	1set	\$ 300.00	50 ✓
5	Windscreen sealant	1PC	\$ 200.00	50 ✓
Special Nett Total S\$:			\$ 910.00	

LABOUR CHARGES

1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts. Also straighten rear spare tyre panel	\$ 1,250.00	1,000 ✓
2	To respray rear bumper, rear tailgate, end panel and spare tyre panel	\$ 1,000.00	900 ✓
3	To remove and install rear tailgate glass	\$ 160.00	120 ✓
4	To apply rustproofing on all damaged parts	\$ 180.00	40 ✓
5	To check wiring system	\$ 100.00	30 ✓
6	To deactivate and activate hybrid battery as a safety precautions	\$ 300.00	120.00 ✓
7	To conduct a standard of operating procedures post repairs scan test as a requirements upon completion of collision repairs	\$ 300.00	120.00 ✓

LABOUR TOTAL S\$:	\$ 3,290.00
TOTAL S\$:	\$ 10,745.68
7% GST	\$ 752.20
GRAND TOTAL S\$:	\$ 11,497.88

Repair day - 5 days
 US

After paint photo

Sum Pin (LKK)

08/12/2020

TP with prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

US
 \$470.00
 5 days.