


PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 73771

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X / /
2	TO DISLODGE ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE THE RENEWAL OF GEARBOX ASSY.	S/N \$ 2,800.00	/ /
3	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT AND RENEW ACCORDINGLY.	S/N \$ 2,400.00	? X n n
4	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 /
TOTAL LABOUR CHARGES		: \$ 6,610.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 7377 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER.	\$	900.00 550 /	
6	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT CHECK.	S/N \$	560.00 X nn	
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00 X nn	
8	TO CARRY OUT PRE AND POST REPAIR DISGNOCTIC CHECK.	S/N \$	384.00 384 /	
TOTAL LABOUR CHARGES		:	<u><u>\$ 8,734.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 73771

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>repair</i>		\$	1,987.00 <i>XR</i>
2 FRONT BUMPER FIXING PARTS <i>Xnn</i>		\$	185.00
3 FRONT BUMPER GRILLE - CENTRE <i>Xsrl</i>		\$	159.00
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>srl</i>		\$	530.00 <i>424</i>
5 RADIATOR GRILLE <i>Xsrl</i>		\$	1,406.00
6 RADIATOR GRILLE CLOSING ELEMENT <i>Xsrl</i>		\$	189.00
7 AIRCON STICKER <i>Xnn</i>	NEC	\$	8.00
8 CAUTION SIGN STICKER <i>Xnn</i>	NEC	\$	14.00
9 NOISE INSULATION <i>Xca</i>		\$	264.00 <i>210.80</i>
10 FRONT ALUMINIUM RIM <i>Xsrl</i>	2	\$	1,397.00
11 STABILIZER BAR <i>Xsrl</i>		\$	384.00
12 ASSEMBLY CARRIER <i>Xsrl</i>		\$	972.00
13 BONDED RUBBER BUSH SET <i>Xnn</i>		\$	103.00
14 PENDULUM SUPPORT <i>Xsrl</i>		\$	88.00
15 GEARBOX SUPPORT - LH/RH <i>? Xsrl</i>	2	\$	44.00
16 STEERING GEAR <i>Xsrl</i>		\$	4,548.00
17 7-SPEED DUAL CLUTCH GEARBOX <i>ca</i>		\$	16,680.00 <i>13344.00</i>
18 TRANSMISSION FLUID <i>Xnn</i>		\$	60.00
19 GEARBOX MOUNTING - LH <i>? Xsrl</i>		\$	249.00
20 GEARBOX CONSOLE - LH <i>? Xsrl</i>		\$	184.00
SUB TOTAL SPARE PARTS	:	\$	29,451.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 7377 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 ENGINE MOUNTING <i>X SVL</i>		\$ 246.00	
22 FRONT NO PLATE <i>X n</i>	S/N	\$ 60.00	
23 SUNDRIES <i>? n</i>		\$ 400.00	<i>163.52</i>
TOTAL SPARE PARTS	:	\$ 30,157.00	
TOTAL LABOUR CHARGES	:	\$ 8,734.00	
GRAND TOTAL	:	\$ 38,891.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hp 90010068
: 07/12/2020 @ 1130
: 6 days + 6 = 12 days in total
: EXCESS: TBA
: Reveal / Resurvey before repair

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT