Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

SJS 7710 U

Your ref:

SHD 6641 U

08 December 2020

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: MUNCHI LEASING PTE LTD

VEHICLE NUMBER: SJS 7710 U

YOUR INSURED VEHICLE NUMBER: SHD 6641 U

ACCIDENT ON 07 Dec 2020 ALONG LOWER KENT BRIDGE ROAD (ROUNDABOUT)

AT ABOUT 14:45 HOURS

We refer to your email/fax dated **08 Dec 2020** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

N-51 AUTOMOTIVE PTE LTD