



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108622

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 15/12/2021  
Reference CC3/CTI20013566/T1es3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1514L  
Insured Veh. GBJ 9383J  
Claim No. SNM20D204912/C02  
Policy No. DMCVSNW00090002000  
Accident Date 08/12/2020  
Inspection Date 09/12/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |                                                                                         |                                                               |                       |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------------|-----------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |                                                                                                                                        |                                                                                         | Ref: CC3/CTI20013566/T1es3q2<br>Date: 15/12/2021<br>Code: CTI |                       |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | <b>Insured Veh.</b>                                                                                                                    | GBJ 9383J                                                                               | <b>Veh. Inspected</b>                                         | SHD 1514L             |
|                                                                                                | <b>Policy No.</b>                                                                                                                      | DMCVSNW00090002000                                                                      | <b>Coverage (\$)</b>                                          | 0.00                  |
|                                                                                                | <b>Claim No.</b>                                                                                                                       | SNM20D204912/C02                                                                        | <b>Excess (\$)</b>                                            | 0.00                  |
|                                                                                                | <b>Assign From</b>                                                                                                                     |                                                                                         | <b>Assign Date</b>                                            | 09/12/2020            |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | <b>Make &amp; Model</b>                                                                                                                | HYUNDAI I30                                                                             | <b>c.c</b>                                                    | 1582                  |
|                                                                                                | <b>Engine No.</b>                                                                                                                      | HIDDEN                                                                                  | <b>Year of Reg.</b>                                           | 2017                  |
|                                                                                                | <b>Chassis No.</b>                                                                                                                     | TMAD281UVHJ142104                                                                       | <b>Colour</b>                                                 | SILVER                |
|                                                                                                | <b>Odometer</b>                                                                                                                        | 290481 KM                                                                               | <b>Steering</b>                                               | IN ORDER              |
|                                                                                                | <b>Brakes</b>                                                                                                                          | IN ORDER                                                                                | <b>Modification</b>                                           | SPORTS RIM            |
|                                                                                                | <b>General</b>                                                                                                                         | GOOD                                                                                    |                                                               |                       |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                |                                                                                                                                        | <b>Size</b>                                                                             | <b>Make</b>                                                   | <b>Balance</b>        |
|                                                                                                | <b>R/H Front Tyre</b>                                                                                                                  | 195/65 R15                                                                              | MAXXIS                                                        | 6 mm                  |
|                                                                                                | <b>L/H Front Tyre</b>                                                                                                                  | 195/65 R15                                                                              | MAXXIS                                                        | 6 mm                  |
|                                                                                                | <b>R/H Rear Tyre</b>                                                                                                                   | 195/65 R15                                                                              | MAXXIS                                                        | 6 mm                  |
|                                                                                                | <b>L/H Rear Tyre</b>                                                                                                                   | 195/65 R15                                                                              | MAXXIS                                                        | 6 mm                  |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.                                                                 |                                                                                         |                                                               |                       |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | <b>Accident Date</b>                                                                                                                   | 08/12/2020                                                                              | <b>Inspection Date</b>                                        | 09/12/2020            |
|                                                                                                | <b>Survey held at</b>                                                                                                                  | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                                                               |                       |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                                                               |                       |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |                                                                                         |                                                               |                       |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                         |                                                               | <b>5 Working Days</b> |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1514L

| Qty                                | Description of Parts                                                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                                                                 |                      |                           |                   |
| 1                                  | FRONT N/S DOOR                                                                                  | TO REPAIR SEE LABOUR | 1,723.60                  | -                 |
| 2                                  | FRONT N/S DOOR HINGES @\$36.10                                                                  | TO REPAIR SEE LABOUR | 72.20                     | -                 |
| 1                                  | REAR N/S DOOR                                                                                   | BENT                 | 2,017.48                  | 2,017.48          |
| 2                                  | REAR N/S DOOR HINGES @\$36.10                                                                   | TO REPAIR SEE LABOUR | 72.20                     | -                 |
| 1                                  | REAR N/S FENDER                                                                                 | TO REPAIR SEE LABOUR | 1,525.73                  | -                 |
| 1                                  | REAR N/S RIM                                                                                    | CUT                  | 246.00                    | 246.00            |
| 2                                  | REAR BUMPER N/S & O/S SIDE BRACKET @\$32.50                                                     | NOT NECESSARY        | 65.00                     | -                 |
| 1                                  | REAR BUMPER                                                                                     | TO REPAIR SEE LABOUR | 811.11                    | -                 |
| 1                                  | FRT N/S DOOR HANDLE OUTER                                                                       | CUT                  | 105.50                    | 105.50            |
| 1                                  | FRT N/S DOOR HANDLE COVER                                                                       | CUT                  | 47.91                     | 47.91             |
|                                    | LESS 20% DISCOUNT                                                                               |                      | -1,337.35                 | -483.38           |
|                                    |                                                                                                 |                      | 5,349.38                  | 1,933.51          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                                                                 |                      |                           |                   |
| 1                                  | SET N/S DOOR STICKER (SN)                                                                       | NECESSARY            | 100.00                    | 60.00             |
| 1                                  | REAR N/S FENDER STICKER (SN)                                                                    | NECESSARY            | 60.00                     | 40.00             |
| 1                                  | SET REAR N/S FENDER INNER SHIELD CLIPS (SN)                                                     | NOT NECESSARY        | 28.00                     | -                 |
| 1                                  | SET REAR BUMPER CLIPS (SN)                                                                      | NOT NECESSARY        | 48.00                     | -                 |
| 1                                  | SUNDRY (SN)                                                                                     | NECESSARY            | 50.00                     | 20.00             |
|                                    |                                                                                                 |                      | 286.00                    | 120.00            |
| <b><u>LABOUR</u></b>               |                                                                                                 |                      |                           |                   |
|                                    | TO CHECK REAR N/S WHEEL ALIGNMENT.                                                              |                      | 80.00                     | 80.00             |
|                                    | TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE FRONT & REAR N/S DOORS INTO NEW SHELL DOOR . |                      | 300.00                    | 60.00             |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                | Description of Parts                                                                                                                                                                                                                                                                                                   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                    | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO CUT/WELD AND HEAT ON THE REAR N/S FENDER .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC.INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR ,FRONT N/S DOOR HINGES ,REAR N/S DOOR HINGES,REAR N/S FENDER AND REAR BUMPER, |           | 1,200.00                  | 700.00            |
|                    | TO PUTTY AND SPRAY PAINTING ON FRONT N/S DOOR ,REAR N/S DOOR ,N/S ROCKER PANEL ,REAR N/S FENDER ,REAR BUMPER .                                                                                                                                                                                                         |           | 1,000.00                  | 800.00            |
|                    | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.                                                                                                                                                                                                                                                             |           | 200.00                    | 30.00             |
|                    |                                                                                                                                                                                                                                                                                                                        |           | 2,780.00                  | 1,670.00          |
| <b>GRAND TOTAL</b> |                                                                                                                                                                                                                                                                                                                        |           | <b>8,415.38</b>           | <b>3,723.51</b>   |

|                                                                             |  |  |  |                 |
|-----------------------------------------------------------------------------|--|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |  |  | <b>2,950.00</b> |
|-----------------------------------------------------------------------------|--|--|--|-----------------|

Report Ref No. CC3/CTI20013566/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 1514L

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1514L

RE-INSPECTION

