



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE

190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*TAILGATE	1		
*TAILGATE OUTER GARNISH	1		
*TAILGATE LOGO	1		
*TAILGATE EMBLEM INFINITI	1		
*TAILGATE REFLECTOR LH / RH	2		
*TAILGATE OUTER HANDLE SWITCH	1		
*TAILGATE INNER LOCK	1		
*TAILGATE LOCK STRIKER	1		
*TAILGATE LOCK SENSOR	1		
*TAILGATE TRIMBOARD	1		
*TAILGATE WEATHERSTRIP	1		
*TAILGATE WINDSCREEN MOULDING	1		
*TAILGATE INNER HANDLE	1		
*REAR BUMPER	1		
*REAR BUMPER SIDE RETAINER LH / RH	2		
*REAR BUMPER REFLECTOR LH / RH	2		
*REAR BUMPER DIFFUSER	1		
*REAR BUMPER DIFFUSER TOW HOOK COVER	1		
*REAR BUMPER SIDE GARNISH LH / RH	2		
*REAR BUMPER SIDE GARNISH RETAINER LH / RH	2		
*REAR END PANEL OUTER	1		
*REAR END PANEL INNER	1		
*REAR END PANEL TOP GARNISH	1		
*SPARE TYRE PANEL	1		
*SPARE TYRE PANEL INSULATOR	1		
*SPARE TYRE PANEL TOP BOARD	1		
*SPARE TYRE PANEL TOOLS TRAY	1		
*SPARE TYRE PANEL LOWER SPLASH COVER	1		
*TAILLAMP LH / RH	2		
*TAILLAMP LOWER BRACKET LH / RH	2		
*EXHAUST PIPE	1		

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*EXHAUST PIPE MOUNTING	1		

\$ -

LESS 10% \$ -

SUBTOTAL \$ -

BALANCE C/F \$ -

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
--------------------	-----	-----------------	---------

BALANCE B/F \$ -

*TAILGATE OUTER GARNISH CLIPS	1	\$ 50.00	
*TAILGATE REFLECTOR CLIP	1	\$ 50.00	
*TAILGATE TRIMBOARD CLIPS	1	\$ 50.00	
*REAR BUMPER CLIPS	1	\$ 50.00	
*REAR BUMPER SIDE GARNISH CLIPS	1	\$ 50.00	
*REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	
*SPARE TYRE PANEL LOWER SPLASH COVER CLIPS	1	\$ 50.00	
*TAILLAMP CLIPS	1	\$ 50.00	
*REAR NUMBER PLATE WITH BASE	1	\$ 100.00	
*TAILGATE REFLECTOR SEAL	1 SET	\$ 60.00	
*TAILLAMP SEAL	1 SET	\$ 80.00	
*TAILLAMP WINDSCREEN SEALANT	1	\$ 100.00	
*TAILLAMP WINDSCREEN INNER SEAL	1	\$ 80.00	
*TAILLAMP WINDSCREEN PRIMER CLEANER	1	\$ 80.00	
*SPARE TYRE PANEL INSULATOR PADDING	1	\$ 320.00	
*REVERSE SENSOR WITH MODULE	1 SET	\$ 200.00	
*REVERSE CAMERA	1 SET	\$ 300.00	

SUBTOTAL \$ 1,720.00

BALANCE C/F \$ 1,720.00

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 1,720.00

TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - REAR	1	\$ 150.00	
TO TRANSFER WINDSCREEN FROM OLD TAILGATE TO NEW	2	\$ 250.00	
TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR	3	\$ 150.00	
TO REMOVE, REFIT AND TEST REVERSE SENSOR	4	\$ 200.00	
TO REMOVE, STRAIGHTEN AND REFIT EXHAUST	5	\$ 300.00	

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 3 OF 3

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
PANEL BEATING ON AFFECTED AREA	6	\$ 2,000.00	
SPRAY PAINTING	7	\$ 2,000.00	
APPLY ANTI RUST ON AFFECTED AREA	8	\$ 150.00	

SUBTOTAL \$ 5,200.00

GRAND TOTAL \$ 6,920.00

