



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE

190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIMS DEPARTMENT

Dense

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

SJKDAAH1541018815

PAGE 1 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*TAILGATE <i>Dented</i>	1	1350	✓
*TAILGATE OUTER GARNISH <i>new</i>	1	290	+
*TAILGATE LOGO <i>new</i>	1	110	✓
*TAILGATE EMBLEM INFINITI <i>new</i>	1	95	✓
*TAILGATE REFLECTOR LH / RH <i>new</i>	2	900	+
*TAILGATE OUTER HANDLE SWITCH <i>new</i>	1	198	+
*TAILGATE INNER LOCK <i>new Dented</i>	1	359	✓
*TAILGATE LOCK STRIKER <i>new</i>	1	88	+
*TAILGATE LOCK SENSOR <i>new</i>	1	240	+
*TAILGATE TRIMBOARD <i>new</i>	1	645	+
*TAILGATE WEATHERSTRIP <i>new</i>	1	284	+
*TAILGATE WINDSCREEN MOULDING <i>new</i>	1	214	✓
*TAILGATE INNER HANDLE <i>new</i>	1	85	+
*REAR BUMPER <i>Dented</i>	1	1296 1080	✓
*REAR BUMPER SIDE RETAINER LH / RH <i>new</i>	2	102	✓
*REAR BUMPER REFLECTOR LH / RH <i>new</i>	2	114	+
*REAR BUMPER DIFFUSER <i>Dented</i>	1	488	✓
*REAR BUMPER DIFFUSER TOW HOOK COVER <i>new</i>	1	38	+
*REAR BUMPER SIDE GARNISH LH / RH <i>LH Dented</i>	2	1016 508	7.2
*REAR BUMPER SIDE GARNISH RETAINER LH / RH <i>new</i>	2	100	+
*REAR END PANEL OUTER <i>Dented</i>	1	785	+
*REAR END PANEL INNER <i>new</i>	1	541	+
*REAR END PANEL TOP GARNISH <i>Dented</i>	1	149	✓
*SPARE TYRE PANEL <i>new</i>	1	1349	+
*SPARE TYRE PANEL INSULATOR <i>new</i>	1	200	+
*SPARE TYRE PANEL TOP BOARD <i>new</i>	1	825	+
*SPARE TYRE PANEL TOOLS TRAY <i>new</i>	1	455	+
*SPARE TYRE PANEL LOWER SPLASH COVER <i>new</i>	1	349	+
*TAILLAMP LH / RH <i>LH Dented</i>	2	1504 752	7.2
*TAILLAMP LOWER BRACKET LH / RH <i>new LH Dented</i>	2	110 55	7.2
*EXHAUST PIPE <i>new</i>	1	1045	✓

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*EXHAUST PIPE MOUNTING <i>new</i>	1	45 x	

6047
 5442.30
 LESS 10% \$ -
 SUBTOTAL \$ -
 BALANCE C/F \$ -

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
--------------------	-----	-----------------	---------

BALANCE B/F \$ -

*TAILGATE OUTER GARNISH CLIPS <i>new</i>	1	\$ 50.00	+
*TAILGATE REFLECTOR CLIP <i>new</i>	1	\$ 50.00	+
*TAILGATE TRIMBOARD CLIPS <i>new</i>	1	\$ 50.00	+
*REAR BUMPER CLIPS <i>new</i>	1	\$ 50.00	✓
*REAR BUMPER SIDE GARNISH CLIPS <i>new</i>	1	\$ 50.00	20
*REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 50.00	20
*SPARE TYRE PANEL LOWER SPLASH COVER CLIPS <i>new</i>	1	\$ 50.00	+
*TAILLAMP CLIPS <i>new</i>	1	\$ 50.00	20
*REAR NUMBER PLATE WITH BASE <i>new</i>	1	\$ 100.00	+
*TAILGATE REFLECTOR SEAL <i>new</i>	1 SET	\$ 60.00	+
*TAILLAMP SEAL <i>new</i>	1 SET	\$ 80.00	+
*TAILLAMP WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	30
*TAILLAMP WINDSCREEN INNER SEAL <i>new</i>	1	\$ 80.00	30
*TAILLAMP WINDSCREEN PRIMER CLEANER <i>new</i>	1	\$ 80.00	+
*SPARE TYRE PANEL INSULATOR PADDING <i>new</i>	1	\$ 320.00	+
*REVERSE SENSOR WITH MODULE <i>David</i>	1 SET	\$ 200.00	✓
*REVERSE CAMERA <i>new</i>	1 SET	\$ 300.00	+

370
 SUBTOTAL \$ 1,720.00
 BALANCE C/F \$ 1,720.00

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 1,720.00

TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - REAR	1	\$ 150.00	70
TO TRANSFER WINDSCREEN FROM OLD TAILGATE TO NEW	2	\$ 250.00	120
TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR	3	\$ 150.00	x
TO REMOVE, REFIT AND TEST REVERSE SENSOR	4	\$ 200.00	50
TO REMOVE, STRAIGHTEN AND REFIT EXHAUST	5	\$ 300.00	x

ESTIMATION QUOTE

BUDGET DIRECT INSURANCE
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLU4482M
MAKE MODEL : INFINITI Q30
REFERENCE : 1AP-202012-14
DOA : 04-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 3 OF 3

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
PANEL BEATING ON AFFECTED AREA	6	\$ 2,000.00	800
SPRAY PAINTING	7	\$ 2,000.00	800
APPLY ANTI RUST ON AFFECTED AREA	8	\$ 150.00	260

SUBTOTAL \$ 5,200.00

1900

GRAND TOTAL \$ 6,920.00

Adrian L
 L/S 11/12/20
 06 Days

Total: 7712.30
 L/S: 6.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: