

 **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0954/2020/NS  
DATE : 5-Dec-20  
WIP : 61387

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT****TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MS MUNIYANDI VANITHA  
ADDRESS : BLK 170 STIRLING ROAD  
#05-1135  
SINGAPORE 140170  
TELEPHONE : HP +65 81125764  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 190094367  
VEHICLE NO : **SML 124 J**  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V  
MODEL YEAR : 30/4/2019  
ENGINE NO : CHZ C29860  
CHASSIS NO : WAUZZZ8V8KA073869  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 3-Nov-20  
PLACE OF ACCIDENT : TEKKA MARKET PARKING LOT



**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 124 J**

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCVORDING TO DAMAGE.	S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER BOTH REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ <del>560.00</del> 280 560	✓
3	TO DISMANTLE AND RENEW REAR BUMPER AND BOTH REAR DOORS. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓ ✓	\$ <del>3,150.00</del> 1750.	
4	TO RESPRAY REAR BUMPER, BOTH REAR DOORS, RHS SILL PANEL AND RHS REAR FENDER. x ✓	\$ <del>4,400.00</del> 2200.	
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	x
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	x
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: \$ <u>8,862.00</u></b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 124 J**

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Regis</i>		\$ 1,944.00	X
2 REAR BUMPER FIXING PARTS <i>new</i>		\$ 191.00	+
3 REAR BUMPER GUIDE SECTION - LH/RH <i>new</i>	2	\$ 32.00	+
4 REAR BUMPER GUIDE SECTION - RH <i>new</i>		\$ 66.00	+
5 REAR DOOR - LH <del>Dented</del> <i>Dented</i>		\$ 2,494.00	X
6 REAR DOOR - OUTER SEAL - LH <del>new</del> <i>new</i>	NEC	\$ 159.00	X
7 BONDING AGENT ?	NEC	\$ 47.00	?
8 CLEANING SOLUTION ?	NEC	\$ 65.00	?
9 REAR DOOR - RH <i>Dented</i>		\$ 2,494.00	X
10 REAR DOOR OUTER SEAL - RH <i>new</i>		\$ 159.00	+
11 BONDING AGENT ?	NEC	\$ 47.00	?
12 CLEANING SOLUTION ?	NEC	\$ 65.00	?
13 REAR DOOR ATTACHMENT PARTS <i>new</i>		\$ 127.00	+
14 REAR DOOR CATCH ?	2	\$ 185.00	?
15 WHEEL HOUSING LINER - RH		\$ 237.00	+
16 REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 88.00	+
17 REAR ALUMINIUM RIM - RH <i>new</i>		\$ 699.00	+
18 SUNDRIES ?		\$ 300.00	?
<b>TOTAL SPARE PARTS</b>	:	<b>\$ 9,399.00</b>	
<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 8,862.00</b>	
<b>GRAND TOTAL</b>	:	<b>\$ 18,261.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*  
SURVEYED DATE : *09/12/20*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 0 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT