

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 29 Apr 2021

Preliminary Advice

Insured Vehicle No	: SLQ8424B		
TP Vehicle No	: SMQ6615T	Accident Date	: 04/12/2020
Make	: TOYOTA C-HR	Assignment Date	: 09/12/2020
Date of Inspection	: 10/12/2020	Est. Duration of Repair	: 2
Inspection At	: TROPICAL SUCCESS AUTO CARE (HQ) BLK 5032 ANG MO KIO AVENUE 3, #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,256.30
Revised Amount	:S\$	1,490.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,490.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :