



Inchcape

Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no. : 6631 1188

UKK

## ESTIMATE

| Account Details                                                                                                               | Account No.                 | Customer Details                                                         |
|-------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------|
| China Taiping Insurance (S) Pte Ltd<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept | S1000003 / ICC11            | M/S Uni-Crane Pte Ltd<br>29 Tuas Avenue 11<br>#02-03<br>Singapore 639089 |
|                                                                                                                               | Document No.<br>0           |                                                                          |
|                                                                                                                               | Document Date<br>07/12/2020 |                                                                          |

| Year | Model   | Variant  | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|----------|------------|----------|------------|---------|---------------------|
| 2020 | KDY231R | TLMKY S5 | 20/08/2020 | GBK5010G | 0          | 58685   | 650D/GBK5010G       |

| Chassis No.       | Engine No. | Terms | SA / Counter     | Vehicle In | Collected On         |
|-------------------|------------|-------|------------------|------------|----------------------|
| JTFAT35YX0K215215 | 1KDB038786 | 60    | Francis Cher T S | --/--/---- | 0.00 --/--/---- 0.00 |

| L | Cd | Job/Parts Description                                                                                                                                                     | Qty | Unit Price | Disc % | Amount       |
|---|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------------|
| 1 | Z  | BP-SUNDRY SUNDRIES<br>POLICY NO.:DMCVSNW00074792000 ACC DATE:04.12.20<br>DRIVE IN : 04.12.20 EXCESS:<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORISED ON: |     |            |        | 50 100.00    |
| 2 | L  | BP-LPO SUPPLY REGN PLATE (PO# )                                                                                                                                           |     |            |        | 80.00        |
| 3 | Z  | BP-SLANT SUPPLY SEALANT (NETT)                                                                                                                                            |     |            |        | 100.00       |
| 4 | B  | BP-LAB2 REPLACE AND REFOCUS HEADLAMP.                                                                                                                                     |     |            |        | 180.00       |
| 5 | S  | BP-SUBLET RESET AND REPROGRAMME ECU.                                                                                                                                      |     |            |        | 180.00       |
| 6 | S  | BP-SUBLET REMOVE AND REINSTALL FRT DASH BORAD<br>ASSY TO ASSIST REPAIR.                                                                                                   |     |            |        | 1296.00      |
| 7 | B  | BP-LAB2 REMOVE AND REINSTALL FRT W/SCREEN<br>TO ASSIST REPAIR.                                                                                                            |     |            |        | 450.00       |
| 8 | B  | BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS<br>TO REPLACE, REPAIR, STRAIGHTEN FRT<br>BUMPER, FRT PANEL ASSY, L/F MIRROR<br>AND AFFECTED PORTION OF CAR.                    |     |            |        | 2880 3600.00 |
| 9 | B  | BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED<br>PORTION OF CAR.                                                                                                                |     |            |        | 1770 2360.00 |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total      |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|                                   |                                       |                                                          | Amount Due |

Customer Copy

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no. : 6631 1188

## ESTIMATE

| Account Details                                                                                                               |            | Account No.                                      |                  | Customer Details                                                         |              |                      |                     |
|-------------------------------------------------------------------------------------------------------------------------------|------------|--------------------------------------------------|------------------|--------------------------------------------------------------------------|--------------|----------------------|---------------------|
| China Taiping Insurance (S) Pte Ltd<br>3 Anson Road<br>#16-00 Springleaf Tower<br>Singapore 079909<br>Attn: Motor Claims Dept |            | S1000003 / ICCI1                                 |                  | M/S Uni-Crane Pte Ltd<br>29 Tuas Avenue 11<br>#02-03<br>Singapore 639089 |              |                      |                     |
|                                                                                                                               |            | Document No.<br>0                                |                  |                                                                          |              |                      |                     |
|                                                                                                                               |            | Document Date<br>07/12/2020                      |                  |                                                                          |              |                      |                     |
| Year                                                                                                                          | Model      | Variant                                          | Reg. Date        | Reg. No.                                                                 | Kilometers   | Wip No.              | Order No. / Remarks |
| 2020                                                                                                                          | KDY231R    | TLMKY S5                                         | 20/08/2020       | GBK5010G                                                                 | 0            | 58685                | 65OD/GBK5010G       |
| Chassis No.                                                                                                                   | Engine No. | Terms                                            | SA / Counter     | Vehicle In                                                               | Collected On |                      |                     |
| JTFAT35YX0K215215                                                                                                             | 1KDB038786 | 60                                               | Francis Cher T S | --/--/----                                                               | 0.00         | --/--/----           | 0.00                |
| L                                                                                                                             | Cd         | Job/Parts Description                            | Qty              | Unit Price                                                               | Disc %       | Amount               |                     |
| 10                                                                                                                            | 1          | T52101-37985 BUMPER SUB-ASSY, FR <i>bt</i>       | 1.00             | 748.90                                                                   |              | 748.90               |                     |
| 11                                                                                                                            | 2          | T81110-37660 HEADLAMP ASSY, RH <i>X SVC</i>      | 1.00             | 1178.70                                                                  |              | 1178.70              |                     |
| 12                                                                                                                            | 3          | T81150-37660 HEADLAMP ASSY, LH <i>CR</i>         | 1.00             | 1178.70                                                                  |              | 1178.70              |                     |
| 13                                                                                                                            | 4          | T53111-37A01 B1 GRILLE, RADIATOR <i>CR</i>       | 1.00             | 595.20                                                                   |              | 595.20               |                     |
| 14                                                                                                                            | 5          | T75315-37080 ORNAMENT, RADIATOR <i>CR</i>        | 1.00             | 70.50                                                                    |              | 70.50                |                     |
| 15                                                                                                                            | 6          | T75311-25100 PLATE, FR NAME, NO.1 <i>bt</i>      | 1.00             | 63.40                                                                    |              | 63.40                |                     |
| 16                                                                                                                            | 7          | T55700-37350 COWL ASSY <i>bt</i>                 | 1.00             | 1194.30                                                                  |              | 1194.30              |                     |
| 17                                                                                                                            | 8          | T55078-37110 COVER SUB-ASSY, FR <i>bt</i>        | 1.00             | 311.80                                                                   |              | 311.80               |                     |
| 18                                                                                                                            | 9          | T87905-37122 ARM SUB-ASSY, OUTER <i>bro</i>      | 1.00             | 600.10                                                                   |              | 600.10               |                     |
| 19                                                                                                                            | 0          | T56121-25040 FRONT W/SCREEN MLDG, <i>new</i>     | 1.00             | 369.40                                                                   |              | 369.40               |                     |
|                                                                                                                               |            |                                                  |                  |                                                                          |              | <b>14,999.30</b>     |                     |
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd                                                                       |            | Acknowledged by Repairer<br>Customer's Signature |                  | Charge Summary                                                           |              | Total 14,657.00      |                     |
| Date:                                                                                                                         |            | Please acknowledge receipt of vehicle            |                  | Parts 6,311.00                                                           |              | GST 7.00% 1,025.99   |                     |
|                                            |            |                                                  |                  | Labour 6,790.00                                                          |              | Less 0.00            |                     |
|                                                                                                                               |            |                                                  |                  | Sublet 1,556.00                                                          |              |                      |                     |
|                                                                                                                               |            |                                                  |                  | Lubrication/Fluid 0.00                                                   |              |                      |                     |
|                                                                                                                               |            |                                                  |                  | Others 0.00                                                              |              | Amount Due 15,682.99 |                     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*Repair before put  
EXCESS: 350  
Repair*