



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Uni-Crane Pte Ltd 29 Tuas Avenue 11 #02-03 Singapore 639089			
			Document No. 38053822					
			Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	KDY231R	TLMKY S5	20/08/2020	GBK5010G	10428	58685	65OD/GBK5010G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTFAT35YX0K215215		1KDB038786	60	Francis Cher T S	15/12/2020	15.27	23/12/2020 8.31	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
10	V	EXC Excess element of insurance repair to be paid by the insured party	8888			-350.00		
11	1	T52101-37985 BUMPER SUB-ASSY, FR	1.00	748.90		748.90		
12	2	T53111-37A01 B1 GRILLE, RADIATOR	1.00	595.20		595.20		
13	3	T75311-25100 PLATE, FR NAME, NO.1	1.00	63.40		63.40		
14	4	T55700-37350 COWL ASSY	1.00	1194.30		1194.30		
15	5	T55078-37110 COVER SUB-ASSY, FR	1.00	311.80		311.80		
16	6	T81150-37660 HEADLAMP ASSY, LH	1.00	1178.70		1178.70		
17	7	T75315-37080 ORNAMENT, RADIATOR	1.00	70.50		70.50		
18	8	T87905-37122 ARM SUB-ASSY, OUTER	1.00	600.10		600.10		
19	9	T56121-25040 FRONT W/SCREEN MLDG,	1.00	369.40		369.40		
20	0	T52012-37170 ARM SUB-ASSY, FR bt (suppl)	1.00	262.20		262.20		
21	1	T87968-0W010 HOLDER, MIRROR, cra (suppl)	1.00	80.10		80.10		
For & on behalf of		Customer's Signature	Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		GST 7.00%			
			Labour		847.74			
			Sublet		Less			
			Lubrication/Fluid		0.00			
			Others		Amount Due			
				12,110.60		12,958.34		

Customer Copy