

SERVICE ESTIMATE

87503 - C00001 SL: SERVICE SALES - PC

Mr Christopher Edward Beal

90 St Francis Road

#04-07

Singapore 328071

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 08/12/2020

WIP No. . : 53991

Veh.In/Out: 07/12/2020

*Tel.No. . : Mobile: 96347906

Reg.No. . : SLJ1963U

Reg.date . : 30/11/2016

Mileage . : 0

Chassis No: YV1FS40LDH2428532

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Edwar

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT FENDER, FRT @ 8w	0	3200.00	0		3,200.00 S	24w ✓
	BONNET, FRT RH DOOR, FRT RH DOOR HARNESS, ETC						
800	TO PUTTY SPRAY PAINT ON FRT @ 7w	0	2800.00	0		2,800.00 S	21w ✓
	BONNET, FRT RH FENDER, FRT RH DOOR, ETC						
287	TO REPLACE CABIN HARNESS x3	0	7200.00	0		7,200.00 S	4080 ✓
287	TO REMOVE & INSTALL DASHBOARD x2	0	7200.00	0		7,200.00 S	2720 ✓ photo
287	TO REMOVE & INSTALL INTERIOR P x3	0	5440.00	0		5,440.00 S	5400 ✓
280	TO CHECK WIRING INCLUDE	0	510.00	0		510.00 S	✓
	RESETTING OF ALL ELECTRICAL MODULES						
	FENDER PANEL FRT RH 5 ✓	1.0 EA	1093.20			1,093.20 S	983.88
	FENDER BRACKET FRT S 1 ✓	1.0 EA	12.00			12.00 S	10.80
	BONNET FRT S60 14- C repair	1.0 EA	2776.60			2,776.60 S	x
	MIRROR BACK COVER RH repair	1.0 EA	300.40			300.40 S	x
	DOOR MIRROR RH S60 1 2 ✓	1.0 EA	700.80			700.80 S	630.72

Patsue

Up 90010068

14 days

10/12/2020 P1520

Rey bea mt

SERVICE ESTIMATE

87503 - C00001 SL: SERVICE SALES - PC

Mr Christopher Edward Beal

90 St Francis Road

#04-07

Singapore 328071

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 08/12/2020

WIP No. : 53991

Veh.In/Out: 07/12/2020

*Tel.No. : Mobile: 96347906

Reg.No. : SLJ1963U

Reg.date. : 30/11/2016

Mileage : 0

Chassis No: YV1FS40LDH2428532

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Christopher Edwar

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	VO32228971/DOOR PANE <i>form</i>	1.0 EA	2409.40			2,409.40 S	2168.46
	GUIDE MOULDING CHROM <i>neu</i>	1.0 EA	322.60			322.60 S	290.34
	DOOR WAIST CHROME RH <i>neu</i>	1.0 EA	269.50			269.50 S	242.35
	DOOR ATTACH SEAL FRT <i>neu</i>	1.0 EA	78.50			78.50 S	70.65
	SOUND DEADENING PAD <i>neu</i>	1.0 EA	525.40			525.40 S	472.86
	D ADHESIVE SEALANT <i>neu</i>	4.0 EA	78.00			312.00 S	280.80
	DOOR CABLE HARNESS F <i>?cut</i>	1.0 EA	240.20			240.20 S	216.18
	CABLE HARNESS FLOOR <i>com</i>	1.0 EA	2008.80			2,008.80 S	1807.92

Gross Total. 37,399.40

Labour Total 26,350.00
 Parts Total 11,049.40
 Package Total 0.00

Net..... 37,399.40
 GST @ 7.0% 2,617.96
 Total..... 40,017.35
 Paid..... 0.00
 Please Pay.. 40,017.35

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

O - L00002 SL: LONPAC INSURANCE BHD LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 1 Inv.date. : 31/12/2020 WIP No. . : 53991 Veh.In/Out: 07/12/2020 *Tel.No. . : 62507388 Reg.No. . : SLJ1963U Reg.date . : 30/11/2016 Mileage . : 0 Chassis No: YV1FS40LDH2428532
Closed by : Richmond Ho Svc Consultant : Remarks : Mr Christopher Edwar	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT FENDER,FRT	0	2400.00	0		2,400.00	S
	BONNET,FRT RH DOOR,FRT RH						
	DOOR HARNESS,ETC						
800	TO PUTTY SPRAY PAINT ON FRT	0	2100.00	0		2,100.00	S
	BONNET,FRT RH FENDER,FRT						
	RH DOOR,ETC						
287	TO REPLACE CABIN HARNESS	0	4080.00	0		4,080.00	S
287	TO REMOVE & INSTALL DASHBOARD	0	2720.00	0		2,720.00	S
287	TO REMOVE & INSTALL INTERIOR P	0	4080.00	0		4,080.00	S
280	TO CHECK WIRING INCLUDE	0	510.00	0		510.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
287	TO REMOVE & INSTALL ROOF LININ nec	0	2040.00	0		2,040.00	S
802	TO TRANSFER FRONT RH DOOR PART nec	0	250.00	0		250.00	S
	FENDER PANEL FRT RH ①	1.0 EA	1093.20	10		983.88	S
	FENDER BRACKET FRT S ②	1.0 EA	12.00	10		10.80	S
	DOOR MIRROR RH S60 1 ③	1.0 EA	700.80	10		630.72	S

suppl
suppl

SERVICE ESTIMATE

0 - L00002	SL: LONPAC INSURANCE BHD	GST Reg.No:M28920628X
LONPAC INSURANCE BHD		0 Page 2
300 BEACH ROAD	Inv.No. . : B&P	
#17-04/07 THE CONCOURSE	Inv.date. : 31/12/2020	
SINGAPORE 199555	WIP No. . : 53991	
	Veh.In/Out: 07/12/2020	
	*Tel.No. . : 62507388	
	Reg.No. . : SLJ1963U	
Closed by : Richmond Ho	Reg.date. : 30/11/2016	
Svc Consultant :	Mileage . : 0	
Remarks : Mr Christopher Edwar	Chassis No: YV1FS40LDH2428532	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	VO32228971/DOOR PANE ⑥	1.0 EA	2409.40	10		2,168.46	S
	GUIDE MOULDING CHROM ⑦	1.0 EA	322.60	10		290.34	S
	DOOR WAIST CHROME RH ⑧	1.0 EA	269.50	10		242.55	S
	DOOR ATTACH SEAL FRT ⑨	1.0 EA	78.50	10		70.65	S
	DOOR TRIM CLIP S60 1 ⑩ <i>Supp nec</i>	20.0 EA	6.40	10		115.20	S
	DOOR CABLE HARNESS F ⑪	1.0 EA	240.20	10		216.18	S
	WHEELARCH FRT RH S60 ⑫ <i>Supp de</i>	1.0 EA	198.50	10		178.65	S
	CABLE HARNESS FLOOR ⑬	1.0 EA	2008.80	10		1,807.92	S
	SOUND DEADENING PAD ⑭	1.0 EA	525.40	10		472.86	S
	D ADHESIVE SEALANT ⑮	4.0 EA	78.00	10		280.80	S

			Gross Total.	25,649.01
Labour Total	18,180.00	Net.....	25,649.01	
Parts Total	7,469.01	GST @ 7.0%	1,795.43	
Package Total	0.00	Total.....	27,444.44	
		Paid.....	0.00	
		Please Pay..	27,444.44	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated