

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING PC4122A [YOUR INSURED] & YP9050R [OUR CLIENT]
ON 08/12/2020.

ESTIMATED REPAIR COSTS FOR YP9050R

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dentrol</i>	1500.00	\$ 2,140.00 ✓
4PCS	TAILGATE HINGE @ \$125.00 EACH <i>NH</i>		\$ 500.00 X
1PC	REAR END PANEL <i>rev</i>		\$ 950.00 X
2PCS	TAIL LAMP LH / RH @ \$520.00 EACH <i>NH</i>		\$ 1,040.00 X
2PCS	TAIL LAMP BRACKET LH / RH @ \$180.00 EACH <i>NH</i>		\$ 360.00 X
1PC	TAIL LAMP WIRE HARNESS <i>NH</i>		\$ 1,680.00 X
1PC	REAR NO. PLATE BRACKET <i>NH</i>		\$ 259.00 X
1PC	REAR NO. PLATE LAMP <i>NH</i>		\$ 125.00 X
2PCS	REAR SIDE GATE LH / RH @ \$2,480.00 EACH <i>NH</i>		\$ 4,960.00 X
2PCS	REAR CHASSIS EXTENSION LH / RH @ \$3,100.00 EACH <i>NH</i>		\$ 6,200.00 X
1PC	FRONT AIR DUCT <i>NH</i>		\$ 850.00 X
1PC	AIR FILTER HOUSING <i>NH</i>		\$ 1,050.00 X
6PCS	CHASSIS BRACKET @ \$359.00 EACH <i>St</i>	600.00	\$ 2,154.00 ✓
	<i>100.00</i>		

2100.00

1785.00

PARTS SUM: \$ 22,268.00

PARTS LESS 15%: \$ 3,340.20

PARTS TOTAL: \$ 18,927.80

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAILGATE PLASTIC GARNISH <i>NH</i>	\$ 1,200.00	X
*	TO SUPPLY '60KM' STICKER <i>NH</i>	\$ 100.00	301-
*	TO SUPPLY '24PAX' STICKER <i>NH NH</i>	\$ 100.00	301-
*	TO SUPPLY REAR STEP BAR <i>NH St</i>	\$ 500.00	* 300
*	TO SUPPLY REAR STEP BAR CAUTION STICKER <i>NH NH NH</i>	\$ 200.00	X
*	TO SUPPLY REAR STEP BAR REFLECTIVE STICKER <i>NH NH</i>	\$ 200.00	* 20
*	TO SUPPLY REAR REINFORCEMENT BAR <i>NH</i>	\$ 2,000.00	X
*	TO SUPPLY REAR REINFORCEMENT BAR STICKER <i>NH</i>	\$ 500.00	X
*	TO SUPPLY REVERSE CAMERA <i>NH</i>	\$ 600.00	X

	2 pcs			
*	TO SUPPLY CHASSIS TOP WOODEN SUPPORT	o/s crack	n/s crack	4000/-
*	TO SUPPLY REAR NO. PLATE & CASING	HW		\$ 5,000.00 ✓
*	TO SUPPLY REAR CANOPY	1 Denon	4340.00	\$ 100.00 X
			LR 800/-	\$ 3,000.00 ✓
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS			\$ 3,000.00 1200
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS			\$ 3,000.00 600
*	TO TUFF COAT DAMAGED AREAS	3670.00		\$ 300.00 40/-
*	TO RNR REAR DECK TO FACILITATE REPAIRS			\$ 2,200.00 1000
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS			\$ 200.00 30/-

LABOUR & S/N TOTAL: \$ 22,200.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 41,127.80

10/12/2020 @ 1700hrs

Not Antenna

1/sum 9 days

Man

LKK Auto

[Signature]

Check P&A prices.

9835.00

4/s 7500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: