WTS Engineering Pte Ltd 8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE:

04/12/20

LOCATION:

Gul Workshop

VEHICLE NO:

XD8406E

Q REF No:

Q20/12/1178

DRIVER:

MOHD ROHIZAT BIN BUANG

DEPARTMENT:

ACCIDENT DATE: 03/12/20

WTS Lorry Crane Department

ATTENTION TO:

PREPARED BY:

Chan Soo Lye

REF No:

JW-1220-51

S/N	Description	Qty	Cost per Unit	Amount S\$
	Spare Parts			
1	PLAST FOOTPLATE LHS	1	773.95	773.95
2	LHS SIDE LAMP	1	78.6	78.60
3	BUMPER LHS	1	623.8	623.80
	Labour Costs			
1	TO DISMANTLE DAMAGED PARTS AND INSTALL FRONT LHS PLAST FOOTPLATE, SIDE LAMP AND FRONT BUMPER LHS. TO RE-ALIGNMENT FRONT BUMPER.	1	450	450.00
			TOTAL:	1,926.35
			Total Amount	SGD 1,926.35

Remarks:

Signature of Department Head

Signature of Claim Department