



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013683/Uvd3q2	
			Date: 30/12/2020	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBF 5002G	Veh. Inspected	SMU 3289A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003621/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	10/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN SERENA HIGHWAY STAR (A)	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JN1EBAC27Z0000502	Colour	WHITE	
Odometer	9812 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	8 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	8 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/12/2020	Inspection Date	10/12/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	