



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 12/10/2020
Vehicle: SMV4079C
Make / Model: LEXUS GS300
Chassis:

No.	Description	Unit	Unit Price	Amount	
Parts Replacement:					
1	REAR PARKING SENSOR UNIT / shuH.	28	\$ 324.00	\$ 972.00	260
2	Bumper REAR PARKING SENSOR RETAINER / CRV	12	\$ 68.80	\$ 134.00	98
3	REAR PARKING SENSOR RETAINER CLAMP X Svc	2	\$ 32.00	\$ 64.00	X
4	REAR BUMPER / det.	1	\$ 1,259.00	\$ 1,259.00	975
5	REAR BUMPER TOWING COVER / CRV.	1	\$ 45.00	\$ 45.00	X
6	REAR BUMPER REINFORCEMENT / BT	1	\$ 525.00	\$ 525.00	X
7	REAR BUMPER REINFORCEMENT GARNISH X Svc	1	\$ 115.00	\$ 230.00	X
8	REAR BUMPER REINFORCEMENT SPONGE / CRV	1	\$ 418.00	\$ 418.00	146.70
9	REAR BUMPER UNDERCOVER X Svc	1	\$ 548.00	\$ 548.00	X
10	BLIND SPOT SENSOR X Svc	2	\$ 1,089.00	\$ 2,179.00	X
11	BLIND SPOT SENSOR BRACKET X Svc	1	\$ 58.00	\$ 58.00	X
12	SMART ENTRY ANTENNA 1 X Svc	1	\$ 267.40	\$ 267.40	X
13	SMART ENTRY ANTENNA 2 X Svc	1	\$ 315.00	\$ 315.00	X
14	SMART ENTRY ANTENNA ECU X Svc	1	\$ 386.00	\$ 386.00	X
15	BOOTLID X R	1	\$ 1,254.00	\$ 1,254.00	X
16	BOOTLID GARNISH X R	1	\$ 598.00	\$ 598.00	X
17	BOOTLID WEATHERSTRIP X Svc	1	\$ 325.00	\$ 325.00	X
18	BOOTLID ANTENNA X Svc	1	\$ 389.00	\$ 389.00	X
19	BOOTLID EMBLEM 'GS300H' / Nec	1	\$ 154.00	\$ 154.00	70.80
20	BOOTLID EMBLEM 'LEXUS' / Nec	1	\$ 156.00	\$ 156.00	70.80
21	BOOTLID EMBLEM X Svc	1	\$ 159.00	\$ 159.00	X
22	REAR END PANEL X Svc	1	\$ 540.00	\$ 540.00	X
23	REAR END PANEL TOP GARNISH X Svc	1	\$ 259.00	\$ 259.00	X
24	REAR FENDER SIDE INNER TRIM LH X Svc	1	\$ 1,356.00	\$ 2,712.00	X
25	TAILAMP X Svc	2	\$ 798.00	\$ 1,596.00	X
26	TAILAMP GARNISH X Svc	1	\$ 68.00	\$ 136.00	X
27	REAR EXHAUST PIPE X Svc	1	\$ 1,698.00	\$ 1,698.00	X
				\$ 17,376.40	2,131.3
			Less 25%	\$ 4,344.10	-25%
			Total	\$ 13,032.30	1,598.48
S/Nett items:					
1	REAR BUMPER CLIPS SET / Nec	1	\$ 50.00	\$ 50.00	30
2	REAR FENDER INNER SHIELD CLIPS SET X Svc	1	\$ 50.00	\$ 50.00	X
3	REAR EXHAUST CHROME / SCR	1	\$ 150.00	\$ 150.00	90
4	REAR END PANEL SEALANT X Svc	1	\$ 80.00	\$ 80.00	X
5	REAR END PANEL TOP GARNISH CLIP X Svc	1	\$ 50.00	\$ 50.00	X
				\$ 380.00	120
Labour to:					

1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	300
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	400
3	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00	30
4	TO REMOVE AND REFIT FRONT BUMPER SENSOR	1	\$ 150.00	\$ 150.00	30
5	REMOVE AND REFIT SMART KEYLESS BUZZER	1	\$ 150.00	\$ 150.00	X
6	PERFORM REAR LIGHTING WIRING TEST FUNCTION	1	\$ 150.00	\$ 150.00	30
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	40
8	TRANSFER BOOTLID MECHANISM	1	\$ 150.00	\$ 150.00	X
				\$ 2,450.00	830
			Parts Replacement Amount	\$ 13,412.30	
			Total Amount for Labour	\$ 2,450.00	
			Total Amount	\$ 15,862.30	

Repair day 3 days

L/S

After paint photo.

Sun Pin (LKL)

11/12/2020

Tpurther pre-judge

1,548.48
120
830

2,548.48
- 20%

2,038.78

L/S
\$2,050
3 days