



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

VEHICLE NO : SKX834T

MAKE MODEL : HONDA CIVIC

REFERENCE : 1AP-202012-13

DOA :

CLAIM TYPE : TP CLAIM

ATTN: MOTOR CLAIMS DEPARTMENT

PAGE 1 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*FRONT BONNET	1	\$ 590.50	
*FRONT BONNET INNER RUBBER	1	\$ 181.00	
*FRONT BONNET INNER SIDE RUBBER LH / RH	2	\$ 164.00	
*FRONT BONNET HINGE LH / RH	2	\$ 352.00	
*FRONT BONNET LOCK	1	\$ 185.00	
*FRONT BONNET LOCK STRIKER	1	\$ 112.24	
*FRONT GRILLE	1	\$ 345.90	
*FRONT GRILLE EMBLEM LOGO	1	\$ 180.00	
*FRONT BUMPER	1	\$ 738.00	
*FRONT BUMPER SIDE BRACKET LH / RH	2	\$ 136.00	
*FRONT BUMPER FOG LAMP LH / RH	2	\$ 601.80	
*FRONT BUMPER FOG LAMP COVER LH / RH	2	\$ 196.00	
*FRONT BUMPER REINFORCEMENT	1	\$ 380.60	
*FRONT HEAD LAMP LH / RH	2	\$ 1,942.80	
*FRONT HEAD LAMP LOWER BRACKET LH / RH	2	\$ 135.80	
*FRONT SUPPORT PANEL	1	\$ 539.40	
*FRONT SUPPORT PANEL TOP COVER	1	\$ 160.80	
*FRONT SUPPORT PANEL SIDE COVER LH / RH	2	\$ 126.70	
*AIRCON CONDENSER	1	\$ 829.00	
*RADIATOR	1	\$ 1,392.00	
*RADIATOR FAN BLADE	1	\$ 158.00	
*RADIATOR FAN COWLING	1	\$ 119.00	
*RADIATOR FAN MOTOR	1	\$ 396.00	
*FRONT FENDER LH / RH	2	\$ 980.00	
*REAR BOOT LID	1	\$ 721.40	
*REAR BOOT LID HINGES LH / RH	2	\$ 196.00	
*REAR BOOT LID EMBLEM LOGO	1	\$ 135.10	
*REAR BOOT LID INNER RUBBER	1	\$ 237.60	
*REAR BOOT LID INNER LOCK	1	\$ 294.50	
*REAR BOOT LID INNER TRIM BOARD	1	\$ 412.20	
*REAR BOOT LID INNER SIDE RUBBER	1	\$ 236.40	

ESTIMATION QUOTE

VEHICLE NO : SKX834T
MAKE MODEL : HONDA CIVIC
REFERENCE : 1AP-202012-13
DOA :
CLAIM TYPE : TP CLAIM

ATTN: MOTOR CLAIMS DEPARTMENT

PAGE 2 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*REAR BOOT LID LAMP LH / RH	2	\$ 660.00	
*REAR BOOT LID TOP SPOILER	1	\$ 589.00	
*REAR TAIL LAMP LH / RH	2	\$ 740.40	
*REAR TAIL LAMP PANEL LH / RH	2	\$ 297.20	
*REAR TAIL LAMP LOWER BRACKET LH / RH	2	\$ 144.00	
*REAR END PANEL	1	\$ 418.30	
*REAR END PANEL TOP GARNISH	1	\$ 191.20	
*REAR FENDER LH / RH	2	\$ 841.50	
*REAR FENDER INNER TRIM BOARD LH / RH	2	\$ 312.80	
*REAR BUMPER	1	\$ 745.30	
*REAR BUMPER SIDE BRACKET LH / RH	2	\$ 160.20	
*REAR BUMPER MUD SHIELD	1	\$ 190.00	
*REAR EXHAUST	1	\$ 808.50	
*REAR EXHAUST ALUMINIUM COVER	1	\$ 164.00	
*REAR EXHAUST CHROME PIPE	1	\$ 420.00	
*REAR SPARE TYRE PANEL	1	\$ 1,045.30	
*REAR SPARE TYRE PANEL TOP COVER	1	\$ 429.90	
*REAR SPARE TYRE PANEL SEALANT	1	\$ 450.00	
*REAR SPARE TYRE TOP SPONGE	1	\$ 248.20	

\$ 22,031.54

LESS 20% \$ 4,406.31

SUBTOTAL \$ 17,625.23

BALANCE C/F \$ 17,625.23

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 17,625.23			
*FRONT GRILLE CLIPS	1	\$ 50.00	
*FRONT BUMPER CLIPS	1	\$ 50.00	
*FRONT BUMPER NUMBER PLATE WITH GARNISH	1	\$ 100.00	
*FRONT SUPPORT PANEL TOP COVER CLIPS	1	\$ 50.00	
*REAR BOOT LID NUMBER PLATE WITH GARNISH	1	\$ 100.00	
*REAR BOOT LID INNER TRIM BOARD CLIPS	1	\$ 50.00	
*REAR TAIL LAMP CLIPS	1	\$ 50.00	
*REAR FENDER INNER TRIM BOARD CLIPS	1	\$ 50.00	
*REAR BUMPER REVERSE SENSOR	1 SET	\$ 200.00	
*REAR BUMPER CLIPS	1	\$ 50.00	

SUBTOTAL \$ 750.00

BALANCE C/F \$ 18,375.23

ESTIMATION QUOTE

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SKX834T
MAKE MODEL : HONDA CIVIC
REFERENCE : 1AP-202012-13
DOA :
CLAIM TYPE : TP CLAIM

PAGE 3 OF 3

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 18,375.23			
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - FRONT AND REAR	1	\$ 250.00	
TO REMOVE AND REFIT AIRCON CONDENSER / RADIATOR TO FACILITATE THE REPAIR	2	\$ 300.00	
TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR	3	\$ 150.00	
TOP UP AIRCON GAS	4	\$ 100.00	
TOP UP COOLANT	5	\$ 100.00	
TO REMOVE, REFIT AND TEST REVERSE SENSOR	6	\$ 200.00	
TO REMOVE, STRAIGHTEN AND REFIT EXHAUST LH / RH	7	\$ 300.00	
PANEL BEATING ON AFFECTED AREA	8	\$ 3,000.00	
SPRAY PAINTING	9	\$ 3,000.00	
APPLY ANTI RUST ON AFFECTED AREA	10	\$ 150.00	

SUBTOTAL \$ 7,550.00

GRAND TOTAL \$ 25,925.23

