

NG SIG KIAT
BLK 633 CHOA CHU KANG NORTH 6
#14-301
SINGAPORE 680633

File No :
Date : 10-December-2020

Estimated cost of repair for vehicle no : SLX5963U TOYOTA COROLLA
Accident involving vehicle no: SLX5963U & SFW6263B on 08.12.2020

Description	Quantity	Cost Price
Rear tailgate Paint X repair	1	\$ 725.00 X
Rear tailgate emblem	1	\$ 61.90 ✓
Rear tailgate badge 'Corolla' / MCL	1	\$ 61.90 ✓
Rear tailgate badge 'Altis' / MCL	1	\$ 61.70 ✓
RH tailgate inner tail lamp / SCR	1	\$ 270.10 ✓
LH tailgate inner tail lamp X NN	1	\$ 270.10 X
Rear tailgate inner lock X SVC	1	\$ 352.00 X
RH tailgate hinge X repair	1	\$ 70.70 X
RH outer taillamp / SCR	1	\$ 379.65 ✓
LH outer taillamp X CRA	1	\$ 379.65 ✓
Rear bumper / RL	1	\$ 480.50 ✓
Rear bumper clips / MCL	1	\$ 32.00 ✓
Rear bumper reinforcement X BT.	1	\$ 386.00 ✓
RH bumper retainer / RL	1	\$ 91.70 ✓
RH bumper bracket X NN	1	\$ 91.70 X
Rear end panel X repair	1	\$ 645.30 X
Rear end panel top trim / RL	1	\$ 197.10 ✓
25% \$ 2402.2		4,557.00
less 20%		\$ 911.40
		\$ 1801.65 3,645.60

Rear tailgate camera X NIV	1	S. Nett	\$ 380.00
Rear bumper parking sensor X NN	1	S. Nett	\$ 260.00 200
Rear bumper sticker / Cut	1		\$ 30 80.00 7

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus taillamp. \$ 35.00 30

To remove rear damaged parts, to jack out rear end panel, rear floor panel and cut out damaged parts, to reweld, reshape and repair rear end panel, RH rear fender, LH rear fender, tailgate, rear bumper to straighten chassis member and adjust body panel alignment \$ 750.00 400.

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material

\$ 700.
1,100.00

To apply anti-corrosion tuff kote .

\$ 100.00 XNN

\$ 6,350.60

T/Party: AIG Asia Pacific Insurance Pte Ltd

2961.65

-20%: 2350

4 Days.
Lumpsum repair
After repair photos.
Guo Qiang.
82880282
15/12/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: