



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

10/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AXA.
Xiao Tong

Accident date: 09/12/2020

Estimated repair cost for vehicle no: SKB6666Z MERCEDES BENZ E200 AVG (R18 LED)

CHASSIS: WDD2130422A255794

S/n	Qty	Items	U/price	Amount
14	2	Rear Tail Lamp <i>new</i>	\$750.00	\$1,500.00 <i>X</i>
15	4	Rear Tail Lamp Clip <i>new</i>	\$6.50	\$26.00 <i>X</i>
16	1	Rear Bumper <i>Deland</i>		(\$1,990.00) <i>1827</i>
17	1	Rear Bumper Lower Lid <i>lt</i>		\$290.00 <i>✓</i>
19	2	Rear Bumper Side Retainer <i>new</i>	\$85.00	\$170.00 <i>✓</i>
20	1	Rear Bumper Center Lower Chrome <i>lt</i>		\$315.00 <i>✓</i>
21	2	Rear Bumper Reverse Sensor <i>Daeng</i>	\$ 260	\$ 520.00 <i>✓</i>
22	1	Rear Bumper Towing Cover <i>new</i>		\$90.00 <i>X</i>
23	1	Rear Bumper Reinforcement <i>new</i>		\$820.00 <i>X</i>
24	1	Rear Bumper Inner Center Bracket <i>Deland</i>		\$115.00 <i>✓</i>
25	1	Rear Bumper Top Beam <i>new</i>		\$320.00 <i>X</i>
26	1	Rear Bumper Leg Sensor Module <i>new</i>		\$450.00 <i>X</i>
31	1	Rear End Panel Assy <i>Repis</i>		\$1,580.00 <i>X</i>
32	1	Rear End Panel Top Garnish <i>new</i>		\$165.00 <i>X</i>
36	2	Rear Exhaust <i>2</i>	\$1,765.00	\$3,530.00 <i>✓</i>
37	1	Rear Centre Exhaust <i>HP</i>		\$1,480.00 <i>✓</i>
38	4	Rear Exhaust Mounting <i>HP</i>	\$45.00	\$180.00 <i>✓</i>
39	2	Rear Exhaust Chrome Pipe <i>Best</i>	\$410.00	\$820.00 <i>X 500</i>

Subtotal :- \$14,201.00

3737

336330

Labour charges

To remove & refit cushion & trim board

\$280.00 *X*

To remove & refit reverse sensor

~~\$100.00~~ *50*

To remove & refit rear & centre exhaust

\$380.00 X

To check wiring

\$100.00 30

Towing

\$150.00 X

Tuff kote

\$150.00 X

Panel beating

\$1,200.00 400

Spray painting

\$1,200.00 400

Subtotal :- \$3,560.00

Total:- \$17,761.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4243.40

L/S: 3.4K

03 Days

3.4K