

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 92313123

Fax: 6452 0614

Vehicle:	XE5209Y
Model:	MITSUBISHI FUSO FV70HJD2VDEA
Chassis:	FV70HJA00157

NO	DESCRIPTION	QTY	UNIT COST PRICE	COST PRICE	SURVEYORS MARKING
1	FRONT GRILL BASE <i>new</i>	1	\$ 510.00	\$ 510.00	X
2	FRONT GRILL LOWER BASE <i>1st</i>	1	\$ 135.00	\$ 135.00	X
3	FRONT BUMPER <i>new</i>	1	\$ 2,250.00	\$ 2,250.00	X
4	FRONT BUMPER HOOK COVER <i>damaged / new</i>	1	\$ 115.00	\$ 230.00	X
5	FRONT BUMPER CENTRE GARNISH <i>new</i>	1	\$ 350.00	\$ 350.00	X
6	HEAD LAMP LHS <i>broken</i>	1	\$ 720.00	\$ 720.00	X
7	HEAD LAMP RHS <i>new</i>	1	\$ 720.00	\$ 720.00	X
8	HEAD LAMP COVER OUTER LHS <i>new</i>	1	\$ 260.00	\$ 260.00	X
9	HEAD LAMP COVER OUTER RHS <i>new</i>	1	\$ 260.00	\$ 260.00	X
10	SIDE STEP RHS <i>new</i>	1	\$ 240.00	\$ 240.00	X
11	SIDE STEP LHS <i>new</i>	1	\$ 240.00	\$ 240.00	X
12	RADIATOR <i>new</i>	1	\$ 4,150.00	\$ 4,150.00	X
			TOTAL:	\$ 10,065.00	

Part by part (6 day repair)

parts - 3945

Labour - 1620

supplymentary - 655

total - 6220 #

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1				
2				
3				
	SPECIAL NETT		\$ -	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEAT- ACCIDENT AREA	\$ 1,500.00	750/-
2	SPRAY PAINT- FRONT BUMPER, FRONT UPPER AND LOWER GRILL, SERVICE DOOR, SIDE STEP X2	\$ 1,500.00	800/-
3	RUST PROOFING	\$ 50.00	40/-
4	REPAIR/CHECK WIRING	\$ 120.00	44
5	ALIGN HEADLAMP AND ALL FRONT ACCIDENT AREA	\$ 120.00	30/-
	TOTAL:	\$ 3,300.00	

PARTS	\$ 10,065.00	
LABOUR	\$ 3,300.00	
SPECIAL NETT	\$ -	
TOTAL	\$ 13,365.00	
GST 7%	\$ 935.55	
FINAL TOTAL	\$ 14,300.55	

15/12/22 @ 1400hrs

Not Antmud
P-A by P-A. 6 days.
Excess \$1500/-

Thank you

2kk And 97237799

Guiding

[illegible]

ESTIMATOR: Kenneth Ding