



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS/ASM20013746/Atce2 Date: 20/10/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	SHD 105R	Veh. Inspected	SJF 9982G	
Policy No.	VFX/P1680520	Coverage (\$)	0.00	
Claim No.	S0M02C7V	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	11/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI LANCER		c.c	1499
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	JMYSRCY2A8U008054		Colour	BLACK
Odometer	210604 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre	205/60 R16		MICHELIN	6 mm
L/H Front Tyre	205/60 R16		MICHELIN	6 mm
R/H Rear Tyre	205/60 R16		MICHELIN	6 mm
L/H Rear Tyre	205/60 R16		MICHELIN	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/01/2020		Inspection Date	09/09/2021
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	