

WORLD AUTO PTE LTD

NO.5, KIM CHUAN LANE

S'pore 537070

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

079120

Attention : Motor Claim Department

Contact : 64193000

Estimate : ES190163

Date : 14/12/2020

Vehicle Num. : SMP 3716K

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 07/11/2020

Claim No. :

Reference :

Policy No. :

*Not Authorised**Primary Repair**4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | |
|-----|---|---------------------------------------|
| 1. | 1 | REAR TAILGATE |
| 2. | 1 | REAR TAILGATE SHUTTLE EMBLEM |
| 3. | 1 | REAR TAILGATE HYBRID EMBLEM |
| 4. | 1 | REAR BUMPER |
| 5. | 1 | REAR BUMPER SIDE INNER FOAM LH |
| 6. | 1 | REAR BUMPER REFLECTOR LENS - LH |
| 7. | 1 | REAR BUMPER REFLECTOR LENS GARNISH LH |
| 8. | 1 | REAR BOOT WEATHER STRIP |
| 9. | 1 | REAR END PANEL |
| 10. | 1 | REAR END PANEL TOP GARNISH |
| 11. | 1 | SMART BUZZER SENSOR |
| 12. | 1 | REAR WINDSCREEN GLASS MOULDING |

List TotalS\$:

20.00% Discount S\$:

SPECIAL NETT ITEMS :

- | | | |
|----|------|--------------------------------------|
| 1. | 1SET | REAR TAILGATE INNER TRIM BOARD CLIPS |
| 2. | 1SET | REAR BUMPER CLIP |
| 3. | 1SET | REAR END PANEL TOP GARNISH CLIPS |
| 4. | 1 | WINDSCREEN SEALANT |
| 5. | 1SET | REVERSE SENSOR |

Special Nett Total S\$:

LABOUR :

REMOVE & REFIT REAR WINDSCREEN GLASS

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

As	1,850.00	✓
na	55.00	✓
na	65.00	✓
Br/na	1,800.00	✓
	160.00	?
Sn	115.00	X
sn	128.00	X
sn	118.00	X
R	480.00	X
Sn	110.00	X
sn	110.00	X
na	110.00	✓

5,101.00

1,020.20

4,080.80

na	30.00	X
na	30.00	✓
na	20.00	X
40sn	80.00	
	280.00	?

440.00

1200

180.00

600 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

NO.5, KIM CHUAN LANE

S'pore 537070

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

079120

Attention : Motor Claim Department

Contact : 64193000

Estimate : ES190163

Date : 14/12/2020

Vehicle Num. : SMP 3716K

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 07/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY INCLUDING DRILL HOLES ON NEW REAR BUMPER FOR INSTALLATION OF NEW SET OF REVERSE SENSORS		151 180.00
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD REAR END PANEL, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS		4001 1,200.00
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME	~ 280.00	X
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES, REINITIALISE HV HYBRID SYSTEM	~ 280.00	X
		PUTTY AND SPRAY PAINT ACCIDENT AFFECTED AREAS		6901 1,000.00
		Labour Total S\$:		3,300.00

E. & O.E.**Total S\$:****7,820.80**

=====

for WORLD AUTO PTE LTD