



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013755/Ktf3q2 Date: 08/02/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 8369D	Veh. Inspected	SMM 292B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003631/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	14/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5 (A)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WAUZZZF58KA028546	Colour	WHITE
	Odometer	35206 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35 ZR19	MICHELIN	8 mm
	L/H Front Tyre	255/35 ZR19	MICHELIN	8 mm
	R/H Rear Tyre	255/35 ZR19	MICHELIN	8 mm
	L/H Rear Tyre	255/35 ZR19	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/12/2020	Inspection Date	21/12/2020
	Survey held at	BLK 160 SIN MING DRIVE #07-09		
	Repairer	CHUAN HO AUTO SERVICE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	