

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: YEO SHEN-YI

11 ROSEWOOD DRIVE
#05-24
SINGAPORE 737939

H/P: 92726868

NO: WQT0801124

DATE: 06 Jan 2021

A/C CODE: C010962

YOUR REF: SKJ5978M

VEH REG NO: SKJ5978M

MAKE/MODEL: TOYOTA LEXUS
NX200T EXECUTIVE

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
-------------	----------	------------	---	--------

S\$

S\$

WE SUBMIT HERewith OUR SUPPLEMENTARY ITEMS TO ABOVE MENTIONED VEHICLE.

DOA: 04/12/2020 @1810 HRS

INVOLVING: SKJ5978M, SFY8759P & SLW9398E

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SFY8759P (INSURED WITH AIG)

1 ✓ FRONT GRILLE SENSOR LH	390	1 PC	490.80	short	490.80	✓
2 ✓ GRILLE HOLE COVER FOR CAMERA (Garnish)		1 PC	35.00	mis	35.00	✓
3 ✓ GRILLE LOWER PORTION		1 PC	302.00	cm	302.00	✓
4 ✓ GRILLE CHROME MOULDING		1 PC	827.60	ngcm	827.60	✓

Total S\$ 1,655.40

Add GST @ 7% 115.88

Grand Total S\$ 1,771.28

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED SEVENTY ONE AND CENTS TWENTY EIGHT ONLY

YEO SHEN-YI

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: YEO SHEN-YI

11 ROSEWOOD DRIVE
#05-24
SINGAPORE 737939

H/P: 92726868

NO: WQT0801127
DATE: 07 Jan 2021
A/C CODE: C010962
YOUR REF: SKJ5978M
VEH REG NO: SKJ5978M
MAKE/MODEL: TOYOTA LEXUS
NX200T EXECUTIVE
SALESMAN:

Description		Quantity	Unit Price	%	Amount
			S\$		S\$
WE SUBMIT HERewith OUR SUPPLEMENTARY ITEMS TO ABOVE MENTIONED VEHICLE					
DOA: 04/12/2020					
ACCIDENT INVOLVING: SKJ5978M & SFY8759P & SLW9398E					
CLAIM TYPE: 3RD PARTY CLAIM AGAINST SFY8759P (INSURED WITH AIG)					
1 ✓	GRILL OUTER COVER LH & RH	2 PC	34.20	nd	68.40
2	TO SPRAY PAINT ON RH FRONT FENDER	1 SVC	200.00	na	200.00
			Total		S\$ 268.40
			Add GST @ 7%		18.79
			Grand Total		S\$ 287.19

TOTAL: SINGAPORE DOLLAR TWO HUNDRED EIGHTY SEVEN AND CENTS NINETEEN ONLY

YEO SHEN-YI

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: YEO SHEN-YI

11 ROSEWOOD DRIVE
#05-24
SINGAPORE 737939

H/P: 92726868

NO: WQT0801115

DATE: 09 Dec 2020

A/C CODE: C010962

YOUR REF: SKJ5978M

VEH REG NO: SKJ5978M

MAKE/MODEL: TOYOTA LEXUS
NX200T EXECUTIVE

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		SS		SS

WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.

DOA: 04/12/2020 @1810 HRS

INVOLVING: SKJ5978M, SFY8759P & SLW9398E

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SFY8759P (INSURED WITH AIG ASIA PACIFIC INS)

1	FRONT BUMPER	1 PC	1,061.80	1,061.80	1061.80
2	FRONT BUMPER CLIPS	10 PC	4.50	45.00	45.00
3	FRONT GRILLE	1 PC	1,211.70	1,211.70	1211.70
4	FRONT BUMPER REINFORCEMENT	1 PC	738.10	738.10	738.10
5	FRONT BUMPER SPONGE	1 PC	99.30	99.30	99.30
6	REAR BUMPER	1 PC	690.20	690.20	690.20
7	REAR BUMPER CLIPS	10 PC	4.50	45.00	45.00
8	REAR BUMPER SIDE RETAINER LH & RH	2 PC	91.80	183.60	183.60
9	REAR UNDER CARRIAGE COVER	1 PC	250.60	250.60	250.60
10	REAR EXHAUST CHROME COVER LH & RH	2 PC	665.20	1,330.40	1330.40
11	REAR EXHAUST PIPE	1 PC	2,109.00	2,109.00	2109.00
12	REAR EXHAUST MOUNTING	1 PC	41.00	41.00	41.00
13	TO CUT, WELD & STRAIGHTEN FRONT & REAR PORTION DUE TO ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	1 SVC	1,000.00	1,000.00	1000.00
14	TO TUFF COAT REPAIRED AREA	1 SVC	100.00	100.00	100.00
15	TO REMOVE & REPLACE EXHAUST PIPE	1 SVC	100.00	100.00	100.00
16	TO SPRAY PAINT ON REPAIRED AREAS	1 SVC	800.00	800.00	800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature